## SURVEY & REMONUMENTATION

JAN 1 9 1999

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			<b>)</b>	
Iron (County)	Located In:	Corner Code		IRON COUNTY MICHIGAN
1. Public Land Survey	T_42N R_33W_	A.B-5	1	RECEIVED FOR RECORD
· · · · · · · · · · · · · · · · · · ·	TR	# 015		98 DEC 28 AMII: 26 Records: L. 7, P. 319
	T R		- 1 1-0	Records: L. 7, P. 319
2. Property Controlling S_	TR TR		-	La Pri
in Section S_	T R		_	Gosteend of Rebeel
3. Miscellaneous S_	TR		_	
Property in Sec. S_	TR		Reg	ister of Deeds Stamp & File Number
4. Lot No, Record	ed Plat		A B	CDEFGHIJKLM
5. Filvate Claims		<del></del>	2	5 - 4 - 3 - 2 - 1
East Meander Corner Sections 7	and 18, T42N, R33W		3	
			4 7	8 9 10 11 12
		•	5	
I Gary I Pisoni in a	field survey on Dec (	0 10.09 do	boroby state 6 - 18	
I, Gary L. Pisoni , in a that under requirements of P.A.				
in lines 1 and 2 above were in	conformance with regul	lations and rules th	erefore as 8 19	
required in the current manual of the Interior, Bureau of Land Mana		· ·	0.1 1.	
corner points mentioned in lines				2928272625
the Michigan Board of Land Sur			stablished, 11	
re-established, monumented, reco	ivered, found as expressed	i pelow:	12 31	32 35   -36
NOTE: Not more than 2 corners, a on this certificate.	I in the same town and range	e, may be recorded	13	
A. Description of original monument and accessories and/or subsequent restoration:  Original corner established in October, 1851 by Guy H. Carleton, U.S. Deputy Surveyor Original Corner; Meander Post				PEER GROUP APPROVED
Original Bearing Trees;		1505 22	links (21,78 feet)	COUNTY REPRESENTATIVE
asp Asp	en 8" N	160°E 24	links (15.84 feet)	
In 1981, Gary L. Pisoni RLS in the East Meander corner posi of said lake.	ound a 1/2" diameter iron tion. Iron pipe set by unk	pipe, 4' from water nown persons and h	s edge, located on the as been used for vario	e East shore of Indian Lake marking ous lot surveys along the East shore
B. Description of corner evider	nce found and/or method a	pplied in restoring o	r reestablishing corne	r:
No evidence of original B.T. The actual measured distan an apparent error in the GL S 89°39'45"E, 2206.29 fe	ce from the quarter corner O distance along this line.	to the East M.C. is The actual measure	not consistent with G ad distance from the N	GLO distances in the area. There is A.C. to the quarter corner is .84 feet.
I accept the above monum	ent as the best available e	vidence for restoring	g the corner position.	
Corner record research on 1	ile with County Represent	ative.		
C. Description of monument for	r corner and accessories e	stablished to perpet	uate locating the posi	tion of the corner:
Replaced iron pipe with a 3/4	4" diameter aluminum rod	monument, 3 feet lo	ong, with a 3" diamet	er aluminum cap stamped as follows:
Iron County Remonumentation	nn. T42N. R33W. M.C., S-	-7, S-18, 1998, NLS	Z/49/ HOIN MINOU	established the following bearing
trees: (All measurements tak		N 10°E	44.30 (66)	THE OF MICHICA
Hemloc	k 11"	N 70°E	25.18 feet 29.37 feet	established the following bearing  OF MICHICAL  GARY L.
Red Ma Steel si		S 61°E East	0.75 feey	PISONI **
98-48 / # //	₹		•	* PISONI LAND * SURVEYOR
Signed by Plany of to	Date	12-21-98		No. No.
Surveyor's Michigan License No	. 27457	FORM	APPROVED BY MICHIGAN STATE	REVISED JAN., 1983
		6.7 P.	3/9	LAND RED LAND REDIGITO OCT., 1995
•		_ , , ,		