

MAR 9 2000

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 42N R 33W	A-2.3 (017)
	T 42N R 34W	M-2.3(006) ✓
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

IRON COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

99 DEC 30 AM 10:31

L.C. Records: 1.8, P.123

*Robert J. Pisoni*  
COUNTY REPRESENTATIVE

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Meander Corner to Section 6, T42N, R33W  
Meander Corner to Section 1, T42N, R34W

I, Gary L. Pisoni, in a field survey on March 30, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 8, 1846, by Austin Burt, U.S. Deputy Surveyor.  
Original Corner; 6" Aspen Meander Corner Post  
Original Bearing Trees:

White Birch 14" S 62 1/4° E 56 lks (36.96 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Restored Meander corner position on the Southeast shore of Chicagon Lake and on line between the Southwest corner of Section 6, T42N, R33W and the Northwest Corner of Section 6, T42N, R33W.

Corner record research on file with County Representative.

PEER GROUP APPROVED

Gary L. Pisoni 12-21-99  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T42N, R34W, R33W, M.C., S-1, S-6, 1999, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Hemlock	9"	N 56° E	4.88 feet
Cedar	8"	N 88° E	7.02 feet
Cedar	4"	S 21° W	15.31 feet
Steel sign post		S 16° W	1.35 feet

99-123  
Signed by Gary L. Pisoni Date 12-28-99

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN/28, 1971  
REVISED MAY/14, 1975  
27457 REVISED JAN, 1983  
REVISED OCT., 1995

