

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 42N R 34W

C-4

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:07

L.C. Records: L. 8, P. 279

Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Quarter Corner to Sections 7 and 8, T42N, R34W

I, Gary L. Pisoni, in a field survey on July 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on October 13, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Sugar	10"	N 85° W	111 links (73.26 feet)
Elm	18"	S 75° E	70 links (46.20 feet)

PEER GROUP APPROVED
Iron Gary L. Pisoni 11-30-00
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

In 1986, found a bent iron pin marking quarter corner position. Replaced bent iron pin with a 5/8" x 30" long rebar, 8" below roadbed surface. Iron pin agrees with plat boundary line to the North. Quarter corner is located in the East lane of a North/South county road.

I accept the iron pin as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Over the top of the existing rebar pin, set a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T42N, R34W, 1/4, S-7, S-8, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees:
(All measurements taken to a nail in side of tree)

Sugar Maple	5"	N 62° E	36.89 feet
Sugar Maple(dbl)	8"	S 35° W	69.02 feet
Rebar	5/8" x 30"	West	38.76 feet
Sugar Maple	9"	N 51° W	54.31 feet
Steel sign post		West	33.26 feet

00-047

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 31, 1975
REVISED JAN. 1983
REVISED OCT. 1995

