

SURVEY & REMONUMENTATION

FEB 21 2001

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Record L. S. P. 211
Robert A. Goodreau
REGISTERED PROFESSIONAL SURVEYOR

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron	Located In:	Corner Code #
	(County)		
1. Public Land Survey		T <u>43N</u> R <u>31W</u>	<u>C-10</u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
4. Lot No. <u> </u> , Recorded Plat <u> </u>			
5. Private Claims <u> </u>			

Register of Deeds Stamp & File Number

I, Robert A. Goodreau in a field survey on March 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-10 Original corner established by John Burt, U.S. Deputy Surveyor, on 14 July 1849.

Original witnesses: W. Pine 18 N83W 25 links
Cedar 14 S82E 33 links

Keith L. Sackett RLS restored corner on 20 May 1985; midway and on line between corners North and South. He set a 1" ID iron pipe (Liber 5, Page 93).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-10 Found 1" ID iron pipe. Set 5/8" iron pin w/ 3.5" aluminum cap inside.

Found witnesses recorded by Sackett as: 8" Cedar S 35° W 54.5' 1/4S, NBT
10" Tamarack N 80° W 7.3' 1/4S, NBT

Corner record research on file with county representative.

PEER GROUP APPROVED
Robert A. Goodreau 1/14/2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-10 Accepted corner as found.

Witnesses: Set 16d nails in above bearing trees at recorded distances.
5" Fir N 59° E 56.00'
Power pole N 23° E 64.70'
Sign post West 1'

Note: Measurements taken to a nail in side of witnesses.

Signed by *R.A. Goodreau*
Surveyor's Michigan License No. 43053

Date July 1, 2000

