

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Records: L. 8, P. 215

Robert A. Goodreau
REGISTERED PROFESSIONAL SURVEYOR

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>43N</u> R <u>31W</u>	<u>G-9</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Robert A. Goodreau in a field survey on March 22, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-9 Original corner established by John Burt, U.S. Deputy Surveyor, on 21 July 1849.

Original witnesses: Hemlock 12 N52W 30 links
Cedar 12 S18E 9 links

Arthur O. Enger RLS replaced 2 found squared cedar-posts w/ a 1" ID x 36" iron pipe w/4" aluminum cap on 21 October 1968.
Posts checked w/ a rotted Cedar stump, which corresponded to an original bearing tree (Liber 2, Page 589).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9 Found corner as described by Enger.

Found witnesses recorded by Enger as: Cedar 5 S 68° W 23 links, "S28 NBT"

Found witnesses used by unknown surveyor: 9" Cedar N 35° W 13.02'
5" Ash S 40° E 13.30'

Corner record research on file with county representative.

PEER GROUP APPROVED
Robert A. Goodreau
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9 Accepted corner as found.

Witnesses: Accepted above witnesses used by unknown surveyor.
7" Balsam Fir N 34° E 18.99'
Sign post N 26° W 2.75'

Note: Measurements taken to a nail in side of witnesses.

Signed by *Robert A. Goodreau*
Surveyor's Michigan License No. 43053

Date July 1, 2000

