

SURVEY &  
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T 43N R 31W	G-11
		T R	
		T R	
		T R	
2. Property Controlling in Section	S T R		
	S T R		
3. Miscellaneous Property in Sec.	S T R		
	S T R		

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PH 1:11

L.C. Records: L. S. P. 29

*Robert J. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Section Corner to Sections 27, 28, 33, 34, T43N, R31W

I, Gary L. Pisoni, in a field survey on October 26, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 21, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner: Cedar Post

Original Bearing Trees:

Cedar	14"	N 48° E	16 links (10.56 feet)
Cedar	14"	S 49° W	42 links (27.72 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Iron Nail in Iron 11-30-2000

PEER GROUP APPROVED  
COUNTY REPRESENTATIVE

No evidence of original B.T.s found.

Restored the corner position from a found iron pin located in the centerline of a North/South access road and in line with the centerline of M-69 to the East.

I accept this position as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Over the top of the existing iron pin, 8" below roadbed surface, set a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R31W, S-27, S-28, S-33, S-34, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Popple	8"	N 56° E	64.06 feet
Popple	7"	S 77° E	59.98 feet
Popple	8"	S 44° W	56.23 feet
Balsam	5"	N 52° W	40.05 feet
Steel sign post		S 79° W	11.4 feet



00-062

Signed by Gary L. Pisoni Date 11-29-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995