LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

•	2.0			11					
<u> Iron</u>	_ Located In:		Corner Code #						
(County)			**						
1. Public Land Survey	TF	R R———							
2. Property Controlling in Section	S 12 T 43N F S 12 T 43N F	R 32W R 32W	14		% A				
3. Miscellaneous Property in Sec.		3							
4. Lot No. , Red 5. Private Claims	corded Plat			I A	egister of De	eds Stamp		J K	L M
	14	4 03/	18/13	2	5	╀╌┆╼╌┼		2	-!
that under requirements of P.A. above were in conformance with instructions of the United States a Court of Law and /or that the other rules of the Michigan Board re-established, monumented, recoverage of the Michigan Board re-established recoverage of the Michigan Board recoverage of the	74, Michigan P.A. of 1970, regulations and rules therefor Department of the Interior, corner points mentioned in lid of Land Surveyors or by	the corner poore as required Bureau of Landines 3, 4 and 5 y a Decree of	d in the current manual of s nd Management or by a decr 5 above were in conformance	and 2 5 survey 5 ee of 6 1	7 — 6 — 1 — 17 — 9 — 20	916	-10 -15 -22	11	-12 9
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town	n and range, I	may be recorded	10—3 11—12—3	29	28	-27	35	-25 -36
A. Description of original m	onument and accessori	ies and/or su	ubsequent restoration:	13		<u></u>		<u> </u>	لبل

(14-Sec. 12) South 1/16 corner between Sec. 12 T43N-R32W and Sec. 7 T43N-R31W. 1943 - Holland, Ackerman & Holland plan G-154-GG for Wisconsin Michigan Power Company shows corner monumented with "pipe marker". 3" Maple S15°E 9.0', 5" Basswood N85°W 20.2', 3" Maple N05°E 13.0'.

(9-Sec. 12) East 1/16 corner, Section 12. 1943 - Holland, Ackerman & Holland plan G-154-GG for Wisconsin Michigan Power Company shows corner monumented with "pipe marker". 8" Birch S54°W 5.9', 4" Ash N20°W 13.5', 6" Birch S25°E 3.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 12) Established the position for the corner midway and on the Range line between Section corner 1334.85' south and Quarter corner 1334.85' north. From the position thus established I found a Wisconsin-Michigan Power Company monument N03°E 6.7' distant, which I did not accept as marking the position for the corner. Removed the WMPCO monument.

(9-Sec. 12) Established the position for the corner midway and on a straight line between Center of Section 12 1319.85' west and Quarter corner 1319.85' east. The WMPCO monument noted on the 1943 plan was not recovered. It may be too far removed from the proper corner position, judging by the mislocation observed at L4, to be easily discovered. Wherever it may be someday found, I do not accept it as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx32" I.pipe wit	h 4" alum. MDNR cap.
Set measuring nail with MDNR	tag in the side of:
10" Sugar N80°E 24.4'	mrkd "1/16S BT"
5" Sugar S05°E 9.15'	do
10" Sugar S41°W 28.7'	do
5" Sugar N08°W 13.9'	do
Set sq'd cedar post adjacent	•
E= 7903987.053 N= 150912.	740

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 7" B.Ash N87°E 5.4' mrkd "1/16S BT" 12" Cedar S19°E 7.8' do 6" Spruce S74°W 6.2' do 4" Cedar N37°W 12.8' do Bearing to cedar is to the lower blaze. Set sq'd cedar post adjacent.

E= 7903592.877 N= 151324.316

COLAND ST

Bearings are magnetic. Coordinat Coord. Ref.=NGS PID RL0240: N		meters (NAD83(2011) E= 7907633.635 m.	Datu	48 05 M/SO	A
Signed by Stephen Synsylval.	Date	07/22/2013		STEPHAN J.	1
Surveyor's Michigan License No. 3390		_	4	LAND	H
For the Michigan Department of Natural	1	SURVEYOR			
	FOR	M APPROVED BY MICHIGAN STATE BOX		No.	S. #