

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 19 T 43N R 32W	8
	S T R	(GCDB 120340)
	S 19 T 43N R 32W	4
	S T R	(GCDB 120360)
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 12/17/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 19) Center-West 1/16 corner, Section 19. Found no record of prior monumentation.

(4-Sec. 19) Northwest 1/16 corner, Section 19. Found no record of prior monumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 19) Established the position for the corner 20 chains, proportionate to the original record
west of the intersection of 1/4 lines of Sec. 19 and on a straight line between said intersection
1320.04' (20.00 ch. US) east and Quarter corner A8 1329.62' (20.145ch. US) west.

(4-Sec. 19) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners. 1/16 corners #1, #3, and #8 are monumented. 1/16 corner #5 is not
monumented. I found a 1"ID I.pipe S32°W 12.65' from the position used for #5. The pipe was not
accepted for controlling the subdivision of the NW1/4 of this section. The position used for #5 is
midway and on a straight line between monumented B7 and the unmonumented intersection of 1/4 lines.
From the monumented #4, I found a 1"ID I.pipe S31°W 7.12' distant, not accepted. I conclude that
whoever set this pipe ran in the W1/16 line incorrectly, without regard to the fractional nature of
the west 1/2 of this section, using positions for 1/16 corners #1 and #8 midway between controlling
corners, rather than establishing them proportionate to the US plat dimensions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" R.Pine N43°E 5.8' mrkd "1/16S BT"
12" R.Pine S67°E 16.45' do
14" W.Pine S01°E 24.0' do
10" R.Pine S68°W 8.25' do
Set sq'd cedar post adjacent.
E= 7894715.784 N= 148191.775

(4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" R.Pine N06°E 4.05' mrkd "1/16S BT"
7" R.Pine S59°E 17.4' do
12" R.Pine S10°W 10.35' do
10" W.Pine N68°W 9.0' do
1" ID I.pipe S31W 7.12', flush.
Set sq'd cedar post adjacent.
E= 7894721.687 N= 148592.278

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref. (adjusted)=NGS PID AA8081: E= 7895147.463m N= 147176.691m

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/28/2016

For the Michigan Department of Natural Resources, Forest Resources Division

