

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 12 T 43N R 33W	4
	S 12 T 43N R 33W	SMC S. of #2
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on SMC 08/11/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 12) Northwest 1/16 corner, Section 12. Not established in the original survey.

(SMC S. of #2) Special Meander corner on the East 1/16 line of Section 12, south of 1/16 corner #2,
Section 12, on the line between Government Lots 1 and 2. Not established in the original survey.
Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 12) Established the corner at the intersection of the West and North 1/16 lines of Section
12. The direction of the West 1/16 line is at mean bearing of the West line of the Section and the N
S 1/4 line, the direction of the North 1/16 line is parallel to a line between Section corner K3 and
Quarter corner L3.

(SMC S. of #2) Found a 1"ID iron pipe, not of record, 1.83' east of the mean of the bearings of the N
S 1/4 line of Section 12 and the East line of Section 12, and 878.71' south of the 5/8" rebar at 1/16
cor. #2 (recorded by the undersigned). Accepted the pipe as a careful and faithful determination of
the direction of the 1/16 line. The pipe is 3' north of the apparent OHWM of the Paint River.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" B.Spruce S57E 9.8' mrkd "1/16S BT"
4" B.Spruce S14W 23.2' do
5" Maple S73W 12.7' do
5" B.Spruce N20W 14.85' do
Squared a 4" Balsam, adjacent.
Bearings are magnetic.

(SMC) Fd. 1"ID iron pipe. Set plastic cap
"Mich DNR PS33986 in the top of the pipe.
Set measuring nail with MDNR tag in the side of:
7" Ash N14E 8.6' mrkd "SMC BT"
6" Ash S36W 14.4' do
12" Ash S85W 10.0' do
4" W.Spruce N29W 11.4' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/21/2011

For the Michigan Department of Natural Resources, Forest Management Division

