

MAR 9 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>43N</u> R <u>35W</u>	<u>G-9</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

99 DEC 30 AM 10:17

L.C. Records: L. 8, P. 49

Robert J. Pisoni
REGISTER

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Section Corner to Sections 21, 22, 28, 27, T43N, R35W

I, Gary L. Pisoni, in a field survey on Nov. 26, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1851 by Harvey Mellen, U.S. Deputy Surveyor
Original Corner: Wood Post
Original Bearing Trees:

Cedar	12"	N 54° W	21 lks (13.86 feet)
Cedar	10"	S 39° E	27 lks (17.82 feet)

PEER GROUP APPROVED
Iron Land from 12-21-99
COUNTY REPRESENTATIVE

On 09/22/64, Donald D. Lappala, RLS USFS, found corner marked by a 36" X 36" by 4" thick concrete slab with a 7/8" iron pin. Corner located on an old fence line running North and West. Recorded in Liber 3, Page 12 of LC records.

1964 Bearing Trees:

Tamarack	5"	S 61° W	7.6 feet (11.5 links)
Cedar	6"	S 11° W	22.9 feet (34.7 links)
Cedar	4"	S 49° E	34.7 feet (52.6 links)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On 11/26/99, found the monument as described above and the following bearing trees:

Tamarack	14"	S 64° W	7.43 feet
Cedar	7"	S 11° W	22.92 feet
Cedar	9"	S 49° E	34.65 feet

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set one (1) reference monument being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R35W, R.M., S-21, S-22, S-27, S-28, South, 2.17 feet, 1999, RLS 27457 from which I established the following new reference objects:

R.M.	5/8" x 30" rebar	North	2.17 feet
	Steel sign post	North	2.57 feet

99-49
Signed by Gary L. Pisoni Date 12-28-99Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

