

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T 43N R 35W	I-8
		T R	
		T R	
		T R	
2. Property Controlling in Section	S T R		
	S T R		
3. Miscellaneous	S T R		
Property in Sec.	S T R		

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:07

L.C. Records: L. 8, P. 276
Gilbert J. Pisoni
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Sections 22 and 23, T43N, R35W

I, Gary L. Pisoni, in a field survey on November 2, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 7, 1851 by Harvey Mellen, U.S. Deputy Surveyor.
Original Corner: Wood Post
Original Bearing Trees:

Sugar	12"	S 81°E	21 links (13.86 feet)
Sugar	12"	N 62°W	22 links (14.52 feet)

PEER GROUP APPROVED
Iron County Peer Group 11-20-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T. s found.

In 1982, found an iron bar marking corner position. The iron bar was set by Hanna Mining Company in the 1950's. Iron bar was destroyed during road construction in 1996. In 1997, I set a railroad spike in blacktop surface replacing the missing iron bar. The railroad spike is located in the East lane of a North/South county road.

I accept the railroad spike as the best available evidence for restoring the quarter corner.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set one reference monument being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R35W, R.M., 1/4, S-22, S-23, N 60° W, 30.15 feet, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Red Maple	3"	N 51°E	60.85 feet
R.M.	5/8" x 30" rebar	S 60°E	30.15 feet
Rebar	5/8" x 30"	S 60°W	50.23 feet
Utility Pole	N69 1496	N 29°W	86.91 feet
Steel sign post		S 60°E	31.0 feet

00-044

Signed by *Gary L. Pisoni*

Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 25, 1971

