

# SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Records: L.S. P. 224

*Robert A. Goodreau*  
REGISTER OF DEEDS

For corners in

<u>Iron</u>	Located in:	Corner Code #
(County)		
1. Public Land Survey	T 43N R 36W	E-1 ✓
	T 44N R 36W	E-13
	T ___ R ___	___
	T ___ R ___	___
2. Property Controlling in Section	S ___ T ___ R ___	___
	S ___ T ___ R ___	___
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	___
	S ___ T ___ R ___	___

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on May 10, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
E-1/E-13 Original corner established by Austin Burt, U.S. Deputy Surveyor, in 1847.

Original witnesses:	Yellow Birch	10"	N 64° E	38 links
	Yellow Birch	14"	N 32° W	40 links
	Hemlock	10"	S 30° W	19 links
	Hemlock	18"	S 40° E	18 links

Donald D. Lappala RLS restored corner position on 9 September 1964 w/ a chiseled (x) in pavement, using 1934 Michigan State Highway project plans and 2 reference monuments. He also set a 2" x 5' concrete filled reference monument w/ bronze tablet (Liber 3, Page 287).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1/E-13 Found RR spike in monument box set by unknown surveyor.

Found reference monument set by Lappala described as: South 34.85'

Found witness recorded by Lappala as: 14" Elm N 40° W 91.7' (138.9 links)

Corner record research on file with county representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1/E-13 Accepted corner as found.

Witnesses:	17" Elm stub	N 34° W	91.41'
	6" Hemlock	S 34° E	64.10' (NBT)
	7" Maple	N 30° E	94.67' (NBT)
	Ref. mon.	South	34.85'
	Sign post	1' South of reference monument	

Note: Measurements taken to a nail in side of witnesses.

Signed by *R.A. Good*  
Surveyor's Michigan License No. 43053

Date July 1, 2000

PEER GROUP APPROVED

*Don Ray d. Peace* 11-14-2000  
COUNTY REPRESENTATIVE

