

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

For corners in

Located In: Iron (County) Corner Code #

1. Public Land Survey T 44N R 33W M-10
T 44N R 32W A-10 ✓
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

00 DEC 22 PM 3: 26
L.C. Records: L. 8, P. 317
Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Section 30, T44N, R32W
Quarter Corner to Section 25, T44N, R33W

I, Gary L. Pisoni, in a field survey on November 30, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 6, 1846 by Austin Burt, U.S. Deputy Surveyor.
Original Corner; Black Ash Post
Original Bearing Trees:
Fir 6" S 62 1/2° E 28 links (18.48 feet)
Hemlock 8" N 60° W 27 links (17.82 feet)

PEER GROUP APPROVED
Iron County Peer Group
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found an old fence line 12' South of the corner position and running approximately East and West, no apparent fence corner marking corner position.

Restored the corner position by single proportionate measurement and on line between the Northeast and Southeast Section corners of Section 25.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar, flush with ground surface, with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T44N, R33W, R32W, 1/4, S-25, S-30, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Cedar	12"	N 81° E	27.87 feet
Ash	7"	S 51° E	21.88 feet
Ash	7"	South	24.02 feet
Ash	6"	S 74° W	26.55 feet
Steel sign post		N 56° E	0.7 feet

00-085
Signed by Gary L. Pisoni Date 12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

