

# SURVEY & REMONUMENTATION

FEB 21 2001

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC -5 PM 12: 50

L.C. Records L. 8, P. 219

*Robert A. Goodreau*  
REGISTERED PROFESSIONAL SURVEYOR

For corners in

Iron _____	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 44N R 33W	I-7
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on May 16, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2			
3													
4		7		8		9		10		11		2	
5													
6		18		17		16		15		14		3	
7													
8		19		20		21		22		23		4	
9													
10		30		29		28		27		26		5	
11													
12		31		32		33		34		35		6	
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-7 Original corner established by Guy A. Carleton, U.S. Deputy Surveyor, in June 1851.

Original witnesses:	Hemlock	10	N24W	31 links
	Sugar	16	S87E	08 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-7 Found 1" iron pipe (bent) in gravel road with traces of wood post underneath. Removed pipe and replaced with a 3/4" iron pin with a 3.5" aluminum cap.

Found witnesses:	8" Twin Soft Maple	N65W	34.50'
	Power pole	N65E	83.90'

Corner record research on file with county representative.

PEER GROUP APPROVED

*Leon Ray L. Rose 11-14-2000*  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-7 Corner: 3/4" iron pin with a 3.5" aluminum cap.

Witnesses:	8" Twin Soft Maple	N 65° W	34.50'
	Power pole	N 65° E	83.90'
	8" Twin Soft Maple	S 02° E	54.08'
	Monitor well	N 42° W	77.60'

Note: Measurements taken to a nail in side of witnesses.

Signed by *Robert A. Goodreau*  
Surveyor's Michigan License No. 43053

Date July 1, 2000

