

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 33W

J-7

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:10

L.C. Records: L. 8, P. 290

Robert J. Pisoni
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Quarter Corner to Sections 14 and 23, T44N, R33W

I, Gary L. Pisoni, in a field survey on November 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in June, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Sugar	10"	S 37° E	29 links (19.14 feet)
Sugar	16"	N 86° W	22 links (14.52 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PEER GROUP APPROVED

Iron County 11-20-2000
COUNTY REPRESENTATIVE

No evidence of original B.T.s found.

Restored the corner position by single proportionate measurement and on line between the Northeast and Northwest Section corners of Section 23.

Found a blue painted boundary line running East and West which is approximately 110 feet North of the corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar, flush with ground surface, with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T44N, R33W, 1/4, S-14, S-23, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Sugar Maple	5"	N 41° E	11.23 feet
Sugar Maple	7"	S 43° E	12.25 feet
Sugar Maple	6"	S 18° W	5.46 feet
Red Maple(triple)	12"	N 64° W	17.52 feet
Steel sign post		S 15° W	0.7 feet

00-058

Signed by

Gary L. Pisoni

Date

11-29-2000

Surveyor's Michigan License No.

27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995