SURVEY & REMONUMENTATION

FEB 21 2001

	SECTION		ECORDATION CERTIFICATE OF Act 74, Mich. P.A. 19	azo COMMENCI	NG YEAR 2000	
or i	corners in	•	,	代とした! Y た!	D FOR RECORD	
_	Iron	Located In:	Corner Code #	50 bes 6	0 011 0 00	
	(County)			00 DEC 2	2 PH 3: 26	10
. Р	Public Land Survey	T_44N R_33W_	M-10	I.C. Xegu	Do: L.8, P. 3	17
		T 44N R 32W	A-10	- 22	المراجع والمحتمد المراجع	
		T R		Sharinais San mada	et of rooms	
P	Property Controlling S_	TR			7.4.2 . 4.44	
		T R T R				
	Miscellaneous S_	TR				
P	Property in Sec. S_	TR		Register of Deed	is Stamp & File Num	ber
٠. ١	ot No, Record	ed Plat				
. Р	rivate Claims			A B C D E	F G R I J K	L M
14404	rter Corner to Continu 20 T	MAN DOOM		2 - 6 - 5	4	i
	rter Corner to Section 30, T4 rter Corner to Section 25, T4			3	 	
				4 - 7 - 8	9	12-
	Gary L. Pisoni , in a	field survey on November	30 , 2000 do hereby state	5		
∍≀aเ า li	nes 1 and 2 above were in	74, Michigan P.A. of 1970, the conformance with regulation	ne corner points mentioned	6 - 18 - 17	16 - 15 - 14	13
эqu	ired in the current manual of	survey instructions of the Ur	nited States Department of	7		
ne l	Interior, Bureau of Land Mana	agement or by a decree of a Co	ourt of Law and for that the	8 19 - 20 :	21 22 23	24 4
orn	er points mentioned in lines	4 and 5 above were in con	formance with the rules of	9 - - - -		
ne :	iviichigan Board of Land Sur Stablished, monumented, rec	veyors or by a Decree of a Covered, found as expressed be	Court of Law; established,		28 - 27 - 26 -	25-
	Table of the state	wered, round as expressed be	iow.	11		
IOT		ll in the same town and range, ma	ay be recorded		33 - 34 - 35	36
	on this certificate.		•	12 31 32 3		30
				13		
۸.	Description of original monu	ment and accessories and/or s	ubsequent restoration:			
	Original Corner;Black Ash Po	n August 6, 1846 by Austin B st	urt, U.S. Deputy Surveyor.			
f	Original Bearing Trees:					
	Fir 6	" \$ 62 1/2° E B" N 60° W	28 links (18.48 feet) 27 links (17.82 feet)		GROUR APPROVE	
			·		ay d. Fran 12 70	der
3,	Description of corner eviden	ce found and/or method applie	ed in restoring or reestablishi	ng corner: COUN	TY REPRESENTATIV	Ε
ļ	No evidence of original B.T.s	found.				
	Found an old fence line 12' (fence corner marking corner	South of the corner position ar position.	nd running approximately Eas	t and West, no appar	ent	
	Decare and all and a second second					
;	Section corners of Section 2	by single proportionate measu 5.	rement and on line between	the Northeast and So	utheast	
1	Corner record research on fil	e with County Representative.				
۶.	Description of monument for	corner and accessories estab	lished to perpetuate locating	the position of the co	orner:	
	as follows: Iron County Rem	5/8" diameter by 30" long rebonumentation, T44N, R33W, I d scribed bearing trees: (All me	R32W, 1/4, S-25, S-30, 200	RLS 27457 from v	aluminum cap stamp vhich I established th	ped ne
	Cedar 1:	2" N 81° E	27.87 feet			
		7" S 51° E 7" South	21.88 feet	anninn	Micana	
		7" South 3" \$ 74" W	24.02 feet 26.55 feet	July Chile Con	Aprile .	
	Steel sign post	N 56° E	0.7 feet	GAR	Y L. T.	
^~	onr			្ត្រីកេ∮្តិ PhS	ONI PAR	
00-0	od by Mary L. From	71	2-19-2000	LA SURV	HD WY TYCA I B	
•				হ ক ্	. <i>(S)</i>	
ourv	eyor's Michigan License No.	27457	FORM APPROVED BY MICHI	SAN STATE BOARD OF PROFESSIO	REVISED MAY 14,19	75
				ERED	BEVISED JAN 19	193
		1.356.1	-n 0 0-	2011/1/10 L	******	