

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> N. <u>34</u> R. <u>W.</u>	<u>B5 & C5</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner B5 (1/4 corner between Sections 7 & 18, T44N, R34W):

Wood post	(Not found. No subsequent monuments found.)
Y. Birch 10 S65W 15	(" " " " accessories ")
Cedar 10 N45E 41	(" " " " " ")

Corner C5 (Section Corner 7, 8, 17, & 18, T44N, R34W):

Wood post	(Not found. No subsequent monuments found.)
Cedar 12 N35E 28	(" " " " accessories ")
Hemlock 12 S44W 6	(" " " " " ")

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner B5: Re-established 11/3/76 proportionately on line between Sec. Cor. 39.285 ch. W and Sec. Cor. 39.925 ch. E. Note: On this section line, the "perpendicular ledge of rocks 20 ft. high" which the original field notes say is 8.285 ch. W of this corner is actually 18.035 ch. W of it.

Corner C5: Re-established 11/2/76 at record true bearing and distance from Sec. Cor. on range line S89°51'W 79.21 ch. This appears to be as consistent with the original field notes as it is possible to be; there being manifest errors in the original survey measurements north and south of this corner which render proportionate measurements impractical.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner B5: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap (Monument set at a slant because of unmovable rock adjacent)

Cedar 6	N26°W (mag.)	7.5 ft.	"1/4S, NBT"
Cedar 7	S19°E (mag.)	2.3 ft.	"1/4S, NBT"
Cedar 8	N23°E (mag.)	4.4 ft.	"1/4S, NBT"

Corner C5: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

Cedar 12	S80°W (mag.)	12.0 ft.	"S18, NBT"
Cedar 14	S16°E (mag.)	50.7 ft.	"S17, NBT"
Red Maple 8	N17°E (mag.)	43.0 ft.	"S8, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE January 25, 1977

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

