

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 34W	C-1.2 (002)
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:03  
L.C. Records: L. 8, P. 251  
*Gary L. Pisoni*  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

North Meander Corner on Net River between Sections 5 and 6, T44N, R34W

I, Gary L. Pisoni, in a field survey on April 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 18, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Elm	6"	N 17°W	8 links (5.28 feet)
Cedar	12"	N 65°E	15 links (9.90 feet)

On 11/5/76, Arthur O. Enger RLS DNR restored the meander corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 3 3/4" diameter aluminum cap stamped as follows: T44N, R34W, M.C., S-6 S-5, 11/5/76, RLS 13581, recorded in Liber 1, Page 522 of LC records.

1976 Bearing Trees:

Cedar	10"	N 76°E	22.2 feet
White Spruce	14"	S 34°E	6.3 feet

PEER GROUP APPROVED

*Gary L. Pisoni 11-30-2000*  
COUNTY REPRESENTATIVE

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/4/2000, found the above described monument and the following bearing trees:

Cedar	12"	N 77°E	22.58 feet
Spruce	16"	S 36°E	7.12 feet

Monument is 10" above ground surface and 20' North of river bank.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam	8"	S 86°W	34.01 feet
Balsam	6"	N 03°E	14.38 feet
Steel sign post		N 53°W	0.65 feet

00-019  
Signed by *Gary L. Pisoni* Date 11-13-2000  
Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28, 1994  
REVISED MAY 14, 1975  
REVISED JAN 1983  
REVISED OCT., 1995

