

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 34W

T 44N R 35W

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

✓ A-2.3n (005)

M-2.3n (001)

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:04

L.C. Records: L. 8, P. 256

Robert J. Pisoni
REGISTERED AS DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

North Meander Corner to Section 1, T44N, R35W and Section 6, T44N, R34W

I, Gary L. Pisoni, in a field survey on April 5, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by William A. Burt, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Tree:

Cedar 9" N 46° E 36 links (23.76 feet)

On 9/29/75, Arthur O. Enger RLS DNR restored the corner position on true section line on the North bank of the Paint River. Set a 1" diameter by 36" long iron pipe with a 3 3/4" diameter aluminum cap stamped as follows: T44N, R35W, R34W, M.C. S-1, S-6, 9/29/75, RLS 13581, recorded in Liber 1, Page 514 of LC Records.

1975 Bearing Trees:

White Birch 6" N 64° E 35.1 feet
Balsam 10" N 28° W 60.4 feet

PEER GROUP APPROVED

Iron County
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/5/2000, found the above described monument located 3 feet from waters edge and 2" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam 13" N 42° W 28.84 feet
Elm 10" N 05° W 57.81 feet
Balsam 5" N 81° E 24.43 feet
Steel sign post North 1.1 feet

00-024

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 22, 1971

