

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located in:	Corner Code #
1. Public Land Survey	T 44N R 35W	K-4	
	T _____ R _____		
	T _____ R _____		
	T _____ R _____		
2. Property Controlling in Section	S _____ T _____ R _____		
	S _____ T _____ R _____		
3. Miscellaneous Property in Sec.	S _____ T _____ R _____		
	S _____ T _____ R _____		

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:00

L.C. Records: L.S.P. 237

Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Sections 11 and 12, T44N, R35W

I, Gary L. Pisoni, in a field survey on March 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in August 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Sugar	16"	N 03° E	40 links (26.40 feet)
Yellow Birch	12"	S 63° E	25 links (16.50 feet)

On June 10, 1969, Donald D. Lappala RLS USFS restored the quarter corner position from the above GLO bearing trees and set a 2" diameter by 5' long concrete filled iron pipe with a 3" diameter bronze tablet stamped as follows: T44N, R35W, 1/4, S-11, S-12, 1969, RLS 12585 recorded in Liber 3, Page 30 of LC records.

1969 Bearing Trees:

Sugar Maple	7"	N 02° W	34.0 feet
Sugar Maple	7"	N 40° E	33.8 feet
Sugar Maple	13"	S 70° E	7.0 feet

PEER GROUP APPROVED

Iron Surveyor 11-30-2000

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the remains of the GLO bearing tree stumps.

On 3/18/2000, found monument as described above and the following bearing trees:

Sugar Maple	8"	N 04° W	33.89 feet
Sugar Maple	7"	N 41° E	33.65 feet
Sugar Maple	15"	S 73° E	6.98 feet

Found existing bearing tree established by the U.S.F.S.

Sugar Maple	9"	S 30° W	8.93 feet
Wood sign post		S 55° W	3.0 feet

Monument is 24" above ground surface and 40 feet East of main access road.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new reference object:

Steel sign post	N 57° E	1.0 feet
-----------------	---------	----------

00-005

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995