

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>44N</u> R <u>34W</u>	<u>A-2</u>
	T <u>44N</u> R <u>35W</u>	<u>M-2</u> ✓
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:01

L.C. Records: L.S. P. 243

Spencer J. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Quarter Corner to Section 1, T44N, R35W
Quarter Corner to Section 6, T44N, R34W

I, Gary L. Pisoni, in a field survey on April 3, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1	6	5	4	3	2	1							
2													
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by William A. Burt, U.S. Deputy Surveyor

Original Corner; Fir Post

Original Bearing Trees:

Sugar	12"	S 59° E	7 links (4.62 feet)
Sugar	12"	N 48° W	17 links (11.22 feet)

On 9/29/75, Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 3/4" diameter aluminum cap stamped as follows: T44N, R35W, R34W, 1/4, S-1, S-6, 9/29/75, RLS 13581, recorded in Liber 1, Page 514 of LC records.

1975 bearing trees:

Red Maple	8"	N 23° E	22.7 feet
Sugar Maple	8"	S 21° W	34.6 feet

PEER GROUP APPROVED

Don M. Pisoni 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/3/2000 found monument as described above and the following bearing trees:

Red Maple	11"	N 24° E	22.93 feet
Sugar Maple	12"	S 23° W	35.07 feet

Found existing bearing trees established by the U.S.F.S.

Red Maple	12"	S 39° E	60.88 feet
Sugar Maple	8"	S 76° W	36.54 feet
Wood sign post		N 43° W	0.5 feet

Monument is 12" above ground surface.

Corner record research on file with County Representative,

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new reference object:

Steel sign post	N 54° E	0.9 feet
-----------------	---------	----------

00-011

Signed by *Gary L. Pisoni* Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28, 1971

NO. REVISED MAY 24, 1975

27457, REVISED JAN, 1983

REVISED OCT, 1995

LIBER 8 PAGE 243

