

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 31W	M9 (GCDB 700300)
	T 45N R 31W	L9 (GCDB 640300)
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/18/16 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M9) Corner common to Sections 24-25 T45N-R31W and Sections 19-30 T45N-R30W. 1969 - Restablished by
A.O.Enger RLS from local evidence and 1933 Marquette County Road Commission notes. Set 1"IDx36"
I.pipe with 4" aluminum cap. B.Spruce 7" S27°E 68.5 links, B.Spruce 7" S23°W 99 links. Found no
subsequent record.

(L9) Quarter corner common to Sections 24 and 25. 1849 - Established by John Burt, Deputy, midway
and on the Section line between Section corners 39.84 chains east and west. Set Maple post. Fir
14" N15°W 32 links, Cedar 12" S55°E 50 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M9) Found the 1969 monument in good condition, the 1969 witnesses no longer evident. Verified the
position of the corner with respect to 1/4 corner M8 2642.13' north (AOE record 40.00 chains) and
being 1.9' west of straight line through M7-M8 (AOE record on line). I note that this position was
used by an unknown surveyor to control the reestablishment of 1/4 corner L9 at least 15 years ago.
I accept the monument as a careful and faithful reestablishment of the position of the original
corner.

(L9) The original post and accessories have been destroyed by road construction. At the position
proportionate to the original record, I found a PK nail with washer driven into the asphalt road
surface, no ID markings visible. Mr. Bunting, an adjacent land owner whose NW property corner this
is, stated that the PK nail was set prior to the construction of his garage, which was built 15
years ago. I accepted the position as a careful and faithful reestablishment of the position of
the corner, removed the PK nail and set a new monument in its place.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M9) Found 1"ID I.pipe with MI Dept. of Conservation
cap. Set measuring nail with MDNR tag in the side
of:

7" Balsam N60°E 15.2' mrkd "S19 NBT"
8" Balsam S44°E 54.95' "S30 NBT"
21" W.Birch S58°W 73.7' "S25 NBT"
Power pole 4531 24R25 N79°W 41.85'
Set sq'd cedar post adjacent.
E= 7913882.625 N= 166460.293

(L9) Set a 5/8" dia.x24" long rebar with yellow
plastic cap MICH DNR PS33986" flush with the road
surface. Set measuring nail with MDNR tag in the
side of:

Power Pole 4531 24L25 N57°W 60.25'
4" Balsam N10°E 43.1' mrkd "1/4S NBT"
9" Balsam S59°E 25.2' do
3" Spruce S25°W 13.8' do
E= 7913081.439 N= 166454.291

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0202: N= 156159.364 m. E= 7917031.370 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/25/2016

For the Michigan Department of Natural Resources, Forest Resources Division

