

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>45</u> ^{N.} XX R. <u>34</u> ^{W.}		<u>E12; E13; and F13</u>
2. PROPERTY CONTROLLING IN SECTION_____ ,T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION_____ ,T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner E12: Wood post Not found. Found a wood post N42°E 78 lks.
 Fir 8 S57W 19) Not found. No subsequent accessories found.
 Aspen 11 N31E 31)
 Corner E13: Sugar post Not found. Found blazed hemlock N33°W 51 lks.
 Y. Birch 20 N34E 29) Not found. No subsequent accessories found.
 Cedar 10 N83W 22)
 Corner F13: Cedar post Not found. Forester's app. cor. N9°W 38 lks.
 Hemlock 16 N30E 22 } Not found. No subsequent accessories found.
 Hemlock 14 N37W 16 }

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner E12: Re-established 8/29/72 on line between section corners 40.277 ch. to N and to S. Wood post found to NE was an approximate corner probably placed by Northern Paper Mills foresters in early 1950's.
 Corner E13: Re-established 8/3/72 proportionately on line between an original section corner 80.052 ch. E and twp. corner 159.104 ch. W. Blazed hemlock probably marked for approx. corner in early 1950's by NPM foresters.
 Corner F13: Re-established proportionately on line between an original section corner 40.026 ch. E and twp. corner 199.130 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.
 Witnesses for Corner E12: Hemlock 16 S28°W (mag.) 25.2 ft. "1/4S, NBT"
 (Variation 0°00') Sugar Maple 10 S16°E (mag.) 30.9 ft. "1/4S, NBT"
 Witnesses for Corner E13: Sugar Maple 5 S34°W (mag.) 5.6 ft. "S5, NBT"
 Y. Birch 8 N48°E (mag.) 19.2 ft. "S33, NBT"
 Y. Birch 6 N46°W (mag.) 28.5 ft. "S32, NBT"
 Witnesses for Corner F13: Red Maple 13 S69°W (mag.) 9.0 ft. "1/4S, NBT"
 Red Maple 8 N15°E (mag.) 18.3 ft. "1/4S, NBT"
 (1 of a clump of 4)

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE December 28, 1973

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581