

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 16 T 45N 34W	1
	S 16 T 45N R 34W	13-14
	S T R	(SMC between Gov't Lots 1 & 2)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 1 12/06/12 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 16) West 1/16 corner between Sections 9 and 16. 1974 - A.O.Enger RLS established the  
position for the corner on line between 1/4 cor. 19.404 ch. East and Sec. Cor. 20.052 ch. West. Set  
1"IDx36" I.pipe with 4" alum. cap. B.Spruce 5" N24E 13.8', B.Spruce 6" S52E 38.0'.

(SMC) Special Meander Corner between Government Lots 1 and 2, on the South 1/16 line of Section 16  
between 1/16 corners #12 and #14. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 16) Found the 1974 monument in good condition. I did not accept the monumented position but  
rather established the position for the corner midway and on the Section line between Section corner  
1301.08' West and Quarter corner 1301.08' East. The 1974 monument is a WITNESS CORNER to this  
position, it being 23.66' east of the 1/16 corner position.

(SMC) Established a witness corner to the position for the corner on the east bank of the Net River,  
on a straight line between 1/16 corner #12 position 1385.66' west and 1/16 corner #14, 1263.67'  
east. The water's edge of the Net River is 37' West of the corner position. The position is not  
intended to mark the OHWM of the Net River.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Found 1"ID I.pipe with 4" MDNR cap and stamped  
to identify the corner as a Witness Corner. The  
1/16 corner is 23.66' West of this monument.  
Set measuring nail with MDNR tag in the side of:  
8" B.Spruce N80E 29.9' mrkd "WC BT"  
B.Spruce S13E 29.3' do  
W.Birch S72W 22.3' do  
Balsam N36W 12.8' do  
Cedar post 23.7' West, at the approx 1/16 cor.  
position. N=170276.305 E=7879053.687

(SMC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
The cap is stamped to identify the position as  
being a WC to the SE1/16 corner, which would be  
61.19' west. Set measuring nail with MDNR tag in  
the side of:  
9" 7" Balsam N49E 11.5' mrkd "WC BT"  
9" 6" Balsam S76E 16.1' do  
7" 8" Cherry S7W 15.8' do  
Set 4" Balsam N61W 4.3' do  
Set sq'd Cedar post adjacent. N=169071.029  
E=7879860.818

Bearings are magnetic. Coordinates are MCS83, in meters

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 01/14/2013

For the Michigan Department of Natural Resources, Forest Resources Division

