SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

Black Spruce

Surveyor's Michigan License No.___

00-008

Signed by

Steel sign post

3"

27457

S 82°E

N 86°F

Date

LAND CORNER RECORDATION CERTIFICATE COMMENCING YEAR 2000 RECEIVED FOR RECORD BROW COUNTY, MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code # Iron 00 DEC -8 PM 1: 00 (County) L.C. Kecaylo I.L. 8, P. 1. Public Land Survey T 45N R 34W A-11 T<u>45N</u> R <u>35W</u> M-11 4 R 2. Property Controlling R in Section 3. Miscellaneous R Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat Private Claims 2 Section Corner to Sections 25 and 36, T45N, R35W 3 Section Corner to Sections 30 and 31, T45N, R34W 4 I, <u>Gary L. Pisoni</u>, in a field survey on <u>March 20</u>, 2000_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as 7 required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the R corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of 9 the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established on September 17, 1846 by William A. Burt, U.S. Deputy Surveyor. Original Corner; Spruce Post Original Bearing Trees: Spruce 6" N 33° E 52 links (34.32 feet) 12" S 18° W 15 links (9.90 feet) Tamarack In August 1851, Guy H. Carleton, U.S. Deputy Surveyor established the following new bearing trees: 6" N 68° W 50 links (33.00 feet) Tamarack 6" S 65° E 65 links (42.90 feet) Spruce On 8/23/72, Arthur O. Enger RLS DNR restored the section corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 4" aluminum cap stamped as follows: T45N, R35W, R34W, S-25, S-30, S-36, S-31, RLS 13581 and recorded in Liber 1, Page 273-274 of LC records. 1972 Bearing Trees: PEER GROUP APPROVED Black Spruce 6" N 67° W 43.4 feet Nay L. Feson 11-30-200 Red Maple 5" S 23° W 68.7 feet REPRESENTATIVE COUNTY Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found On 3/20/2000 found monument as described above and the following bearing trees: S 23°W 68.90 feet Red Maple 8" 9" N_70°W 42.47 feet Spruce Found existing bearing tree established by the U.S.F.S.: Red Maple 7" S 63°W 71.00 feet N 35° W 1.25 feet Steel sign post Monument is 12" above ground surface. Corner record research on file with County Representative. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

49.28 feet

0.85 feet

GARY L.

PISONI

*