

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

40.

For corners in

Iron

(County)

Located in:

Corner Code #

1. Public Land Survey

T 46N R 34W MC East of H7

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Aug 03 1998

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(MC) Meander corner on West side of Spring Lake on the line between Sections 15-22. Corner established in 1852 by Zelotes B. Searles: "N89 deg. 50'E corrected...68.60 Intersect lake and set post. Spruce 4 S55W 45, Tan 6 N35W 7." January 8, 1954 record of Northern Paper Mills at Ned Lake Timber and Land Co. state: "Dec. 1930 H. Cole and R. Sillers found the Tan. NW to be a 7" stub with iron marks. Jan. 1954: D. Buell and H. Gerry found old marks and the Tan NW as a stub with Iron Marks visible. Set a [Tamarack] post from this old B.T., but no bottom to muck along lake shore, so post may disappear. Set new B.T. Spruce 4 N56W 37."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC) Recovered the 1954 tamarack post at record bearing and distance from the stump remains of the original tamarack BT and the stump remains of the 1954 spruce. No iron marks were visible on the original. The bole of the 1954 witness was found down on the ground adjacent to its stump and was found scribed "MC". The post is located approx. 2 ft. off shore in approx 3 ft. of water. The top of the post is about 6" below the water's surface. Left the post in place and placed a WITNESS CORNER in more stable soil 30.00' Westerly of the post and on a line of mean true bearing between the post and the quarter corner common to Sections 15-22. I observed the true bearing of this line: S89 deg. 17'59"W. At the position of the WITNESS CORNER, I placed a 1" I.D. x 32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, stamped as follows: T46N R34W S15 S22 MC 30.00 ft (arrow east), PS 33986 8/3/98. Corner placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set 1" pipe with 4" MDNR cap for a WITNESS CORNER from which the following are blazed and scribed:

4" B. Spruce N49E 9.7' "MC BT"
3" Tamarack South 13.7' do
3" Tamarack S68W 11.1' do
5" Tamarack N27W 7.6' do

Placed a squared B.Spruce post adjacent.
Distances are to meas. notch. Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/29/98

For the Michigan Department of Natural Resources - Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1986