

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T 46N R 35W	H-11 (003)
		T R	
		T R	
		T R	
2. Property Controlling in Section	S T R		
	S T R		
3. Miscellaneous Property in Sec.	S T R		
	S T R		

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

CO DEC -8 PM 1:04

L.C. Records: L. 8, P. 259

Gary L. Pisoni
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

East Meander Corner Between Sections 27 and 34, T46N, R35W
(613 feet East of Quarter corner)

I, Gary L. Pisoni, in a field survey on September 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Meander Corner; 20" White Pine

Original Bearing Tree:

White Pine 10" S 13° W 15 links (9.90 feet)

On 5/24/67, Donald D. Lappala RLS USFS restored the meander corner position from the remains of the original bearing tree. Set a 2" diameter by 5' long iron pipe with a 3" diameter bronze tablet stamped as follows: T46N, R35W, M.C., S-27, S-34, 1967, RLS 12585, recorded in Liber 3, Page 208 of LC records.

1967 Bearing Trees:

Cedar	10"	N 34° E	29.0 feet
Ledge	Chiseled 'x'	S 38° E	35.7 feet

PEER GROUP APPROVED

Gary L. Pisoni 11-30-2000

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 9/12/2000, found the above described monument and the following bearing tree:

Cedar	16"	N 40° E	28.96 feet
-------	-----	---------	------------

Monument is 24" above ground surface and 7' from waters edge.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam	9"	N 87° E	10.12 feet
Balsam	8"	S 04° W	5.76 feet
Steel sign post		S 38° E	1.75 feet

00-027

Signed by *Gary L. Pisoni* Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1974

