

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970

For corners in

IRON

(county)

Located in:

Corner Code#

BATES TOWNSHIP

1. Public Land Survey

T 46 N, R 35 W C-9 (SW SEC. 20)

2. Property controlling
in Section

S

3. Miscellaneous

S

Property in Sec.

S

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -4 AM 10: 08

L.C. Records: L. 8, P. 180

Steven R. Applekamp
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

CORNER COMMON TO SECTIONS 19,20,30,29, T 46 N, R 35 W

I, STEVEN R. APPLEKAMP in a field survey on NOVEMBER 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by decree of a Court of law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL CORNER ESTABLISHED BY HARVEY MELLE, U.S. DEPUTY SURVEYOR ON JUNE 12, 1851.

ORIGINAL BEARING TREES: HEMLOCK HEMLOCK
16" 7"
S 17°W N 17°E
15 LINKS 15 LINKS

1968 DONALD D. LAPPALA P.S. 12585 SET A 2" I.D. BY 5 FEET LONG GALVANIZED IRON PIPE WITH A BRONZE TABLET STAMPED AS FOLLOWS: T46N, R35W, 19,20,30,29, 1968, RLS 12585 RECORDED IN LIBER 3, PAGE 191. AFTER RECOVERING TWO ORIGINAL BEARING TREES HE MADE THE FOLLOWING BEARING TREES.

| | | |
|--------|----------|--------|
| CEDAR | RED PINE | SUGAR |
| 11" | 13" | 6" |
| N 11°W | N 89°E | S 39°W |
| 40.0' | 65.5' | 8.0' |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CORNER IN GOOD CONDITION AS RECORDED IN 1968 AS PER LAND CORNER RECORD ACCEPTED CORNER POSITION AS IT MATCHED THE BEARING TREES FOUND.

| | |
|----------|----------|
| EXISTING | EXISTING |
| R-PINE | MAPLE |
| 21" | 8" |
| S 87°E | S 38°W |
| 65.42' | 7.87' |

PEER GROUP APPROVED

Iron Range & Ligon 11-30-2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

THE CORNER IS A 3" BRONZE TABLET ON A 2" GALV. PIPE APPROX. 1.5 ABOVE THE GROUND STAMPED AND IN THE ORIGINAL POSITION PER THE 1968 LAND CORNER RECORDATION CERTIFICATE. WE MADE THE FOLLOWING REFERENCES. (ALL MEASUREMENTS TAKEN TO NAIL IN SIDE OF TREE)

| | | | |
|--------|--------|---------|------------|
| MAPLE | BALSAM | Y-BIRCH | STEEL SIGN |
| 5" | 9" | 7" | POST |
| N 38°E | S 17°E | N 76°W | SOUTH |
| 24.85' | 37.73' | 25.47' | 0.85' |



Signed by

Steven R. Applekamp

Date NOVEMBER 9, 2000

Surveyor's Michigan License No. _____

43045