

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filling Requirement of Act 74, Mich. P.A. 1970

For corners in

IRON

(county)

Located in:

Corner Code#

BATES TOWNSHIP

1. Public Land Survey

T 46 N, R 35 W

C-11 (SW SEC. 29)

2. Property controlling
in Section

S

3. Miscellaneous

S

Property in Sec.

S

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -4 AM 10: 03

L.C. Records: L. 8, P. 183

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

CORNER COMMON TO SECTIONS 29,30,31,32, T 46 N, R 35 W

I, STEVEN R. APPLEKAMP in a field survey on NOVEMBER 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by decree of a Court of law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL CORNER ESTABLISHED BY HARVEY MELLEN, U.S. DEPUTY SURVEYOR ON JUNE 12, 1851.

ORIGINAL BEARING TREES:

SPRUCE	SPRUCE
12"	12"
N 83°E	S 81°W
21 LINKS	27 LINKS

1982 GARY PISONI P.S. 27457 SET A STANDARD 2" I.D. BY 30" LONG SPLIT BASE ALUMINUM MONUMENT STAMPED AS FOLLOWS: T. 46N., R. 35W., S-30, S-29, S-31, S-32; 1982; R.L.S. 27457, RECORDED IN LIBER 5, PAGE 13 OF L.C. RECORDS. HE ESTABLISHED CORNER POSITION BY DOUBLE PROPORTIONATE MEASUREMENTS FROM THE NORTH MEANDER CORNER AND THE QUARTER CORNER BETWEEN SECTIONS 31 AND 32, THE QUARTER CORNER BETWEEN SECTIONS 29 AND 32 AND THE QUARTER CORNER BETWEEN SECTIONS 30 AND 31. HE MADE THE FOLLOWING BEARING TREES:

SUGAR	CEDAR	SUGAR	STEEL SIGN
12"	14"	6"	POST
S 65°E	S 31°30'W	N 80°30'W	S 69°30'W
4.45'	36.04'	19.76'	2.02'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CORNER IN GOOD CONDITION AS RECORDED IN 1983 AS PER ACT 74, ACCEPTED CORNER POSITION AS IT MATCHED THE BEARING TREES FOUND.

EXISTING	EXISTING	EXISTING	EXISTING
MAPLE	CEDAR	MAPLE	STEEL SIGN
14"	16"	7"	POST
S 56°E	S 42°W	N 70°W	WEST
4.45'	35.75'	19.74'	2.00'

PEER GROUP APPROVED

Iron County Peer Group 11-30-2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

THE CORNER IS A 2" ALUM PIPE WITH A 3" CAST ALUMINUM CAP STAMPED AND IN THE ORIGINAL POSITION PER THE 1983 ACT 74 LAND CORNER RECORDATION CERTIFICATE. WE MADE THE FOLLOWING ADDITIONAL REFERENCES: (ALL MEASUREMENTS TAKEN TO NAIL IN SIDE OF TREE)

MAPLE	MAPLE
8"	7"
N 51°E	N 72°W
37.50'	29.48'



Signed by

Steven R. Applekamp

NOVEMBER 9, 2000

Surveyor's Michigan License No.

43045