SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

		RNER RECORDATION CE	. P.A. 1970
For corners in IRON	Located In:	Corner Code#	COMMENCING YEAR 2000 RECEIVED FOR RECORD IRON COUNTY, MICHIGAN
BATES TOWNSHIP 1. Public Land Survey	T 46 N, R 35 W	E-9 (SW SEC.21)	no pro 1. AM In: NO
. •			L. C. Regardo: L. 8, P. 186
in Section 3. Miscellaneous	SS		ন এক্ষালোকতা কর্ম ছক্ষ্মান্ত
Property in Sec.	5		Register of Deeds Stamp & File Number
4. Lot No , Recorded 5. Private Claims	i Plat		1 A B C D E F G H I J K L M
CORNER COMMON TO SECTIONS 20,21,28,29, T 46 N, R 35 W 3			
I, STEVEN R. APPLEKAMP in requirements of P.A. 74, Michigan P.A. conformance with regulations and rule of the United States Department of the and/or that the corner points mentione Michigan Board of Land Surveyors or monumented, recovered, found as expenses.	A. of 1970, the corner points in is therefore as required in the e Interior, Bureau of land Man d in lines 3,4 and 5 above we by Decree of a Court of Law;	nentioned in lines 1 and 2 above we current manual of survey instruction agement of by decree of a Court of re in conformance with the rules of	t under 4 7 8 9 10 11 12 12 15 16 16 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18
NOTE: Not more than 2 corners on this certificate.	s, all in the same town and	d range, may be recorded	9 10 30 29 28 27 26 25
A. Description of original monu			12 31 32 33 34 35 36
ORIGINAL CORNER ESTABL JUNE 12, 1851.		N, U.S. DEPUTY SURVEYOR ON	
ORIGINAL BEARING TREES:	CEDAR HEMLO 16" 18" N 84°W S 43°E 33 LINKS 24 LINK		PEER GROUP APPROVED Then Juny 1, Juny 01-30 - Junes COUNTY REPRESENTATIVE
1968 DONALD D. LAPPALA P.S. 12585 RESTORED CORNER FROM FOUND EVIDENCE WHICH INCLUDED THE REMAINS OF THE ORIGINAL BEARING TREES. HE SET A 2° I.D. BY 5 FEET LONG GALVANIZED IRON PIPE WITH A 3" BRONZE TABLET STAMPED AS FOLLOWS: T.46N., R.35W.; S-20, S-21, S-29, R.L.S. 12585; 1968. RECORDED IN IRON COUNTY L.C. RECORDS HE MADE THE FOLLOWING BEARING TREES.			
SUGAR	SUGAR CEDAR		OF I
7" N 45°W 36.9'	4" 12" N 10°E S 21°W 20.7' 55.0'		SINTE OF MICHIGA
B. Description of corner eviden		applied in restoring or reestabli	
FOUND CORNER IN GOOD CONDITION AS RECORDED IN 1968 AS PER LAND CORNER RECORD, ACCEPTED CORNER POSITION AS IT MATCHED THE BEARING TREES FOUND. EXISTING EXISTING EXISTING			
EXISTING SUGAR	EXISTING EXISTING CEDAR SUGAR	•	POFESSIONAL
8" N 13°E 20.72'	15" 15" S 24°W N 38°W 54.98' 36.78'	•	
C. Description of monument for	comer and accessories e	established to perpetuate locati	ng the position of the corner:
STAMPED AND IN THE O	RIGINAL POSITION PER TI	ALV. PIPE APPROX. 1.5 ABOVE HE 1968 LAND CORNER RECOR NCES.(ALL MEASUREMENTS TA	THE GROUND DATION CERTIFICATE. KÉN TO NAIL IN SIDE OF TREE)
MAPLE	STEEL SIGN		
8" N 81°E 27.03'	POST NORTH 0.85'		
Signed by	R.D 0.=	Da	to NOVEMBER 9, 2000
Signed bySurveyor's Michigan License No.	0. 43045	Da	110

C_r, , :