

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 35W	G-10
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

DEC -8 PM 1:05
L.C. Records: L.S.P. 262
Gilbert & Sons
REGISTERED LAND SURVEYORS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Sections 27 and 28, T46N, R35W

I, Gary L. Pisoni, in a field survey on September 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5		4	3	2	1						
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Tamarack	6"	S 67 E	37 links (24.42 feet)
Tamarack	6"	N 72 E	31 links (20.46 feet)

On 4/9/63, Donald D. Lappala RLS USFS restored the corner position from the found above bearing trees and set a 2" diameter by 5' long iron pipe with a 3" bronze tablet stamped as follows; T46N, R35W, 1/4, S-27, S-28, 1963, RLS 12585, recorded in Liber 3, Page 200 of LC records.

1963 Bearing Trees:

Cedar	16"	N 73 E	56.4 feet
White Pine	21"	S 82 E	20.5 feet
Cedar	8"	S 67 E	34.4 feet

PEER GROUP APPROVED

Iron Range, Inc. 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the above original bearing trees.

On 9/12/2000, found the above described monument and the following bearing trees:

Cedar	20"	N 75 E	56.2 feet
White Pine	24"	S 79 E	20.26 feet
Cedar	15"	S 64 E	34.35 feet
Wood sign post		S 73 W	4.0 feet

Monument is 24" above ground surface and 6' from waters edge.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new reference object:

Steel sign post	South	0.75 feet
-----------------	-------	-----------

00-030

Signed by

Gary L. Pisoni

Date

11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL LAND SURVEYORS

