

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T. <u>46N</u> R. <u>35W</u>	<u>G-11</u>
	T. <u> </u> R. <u> </u>	<u> </u>
	T. <u> </u> R. <u> </u>	<u> </u>
	T. <u> </u> R. <u> </u>	<u> </u>
2. Property Controlling	S. <u> </u> T. <u> </u> R. <u> </u>	<u> </u>
in Section	S. <u> </u> T. <u> </u> R. <u> </u>	<u> </u>
3. Miscellaneous	S. <u> </u> T. <u> </u> R. <u> </u>	<u> </u>
Property in Sec.	S. <u> </u> T. <u> </u> R. <u> </u>	<u> </u>

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:04

L.C. Records: L. 8, P. 261

G. L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Section Corner to Sections 27, 28, 33, 34, T46N, R35W

I, Gary L. Pisoni, in a field survey on September 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Spruce	12"	S 28° E	7 links (4.62 feet)
Cedar	6"	N 72° W	20 links (13.20 feet)

On 5/17/63, Donald D. Lappala RLS USFS restored the corner position by a found 3"x3"x36" long cedar stake at record bearing and distance from the remains of the original bearing trees, set a 2" diameter by 5' long iron pipe with a 3" bronze tablet stamped as follows: T46N, R35W, S-27, S-28, S-33, S-34, 1963, RLS 12585, recorded in Liber 3, Page 207 of LC records.

1963 Bearing Trees:

Cedar	8"	S 20°W	13.8 feet
Black Spruce	10"	S 55°E	14.0 feet
Black Spruce	7"	S 16°30'W	25.8 feet

PEER GROUP APPROVED

Iron Gary L. Pisoni 11-30-2000

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 9/12/2000, found the above described monument and the following bearing trees:

Spruce	10"	S 17°W	25.61 feet
Cedar	15"	N 23°W	13.74 feet
Wood sign post		N 68°W	1.35 feet

Monument is 24" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Cedar	10"	N 14°E	6.19 feet
Balsam	11"	S 83°E	25.99 feet
Steel sign post		N 57°E	1.0 feet

00-029

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS CAN. 28, §571

