1. Pupplet Land Survey  T 18 p W	P. Chairn D For co	OVED LAND CORNER  A. 345 of 1990  man Julie  ote Nov. 13, 1996  priners in ackson  (County)	LAND CORNE	SECTION 30, RIVES R RECORDATION CERT rement of Act 74, Mich. P	TIFICATE	#2021149 Liber 1532 Page 422 Page 1 of 2 Jackson Co., MI Recorded 11/26/96 02:14P Jerry McDevitt Register of De <b>eds</b>
2. Property Controlling S T F F S S Miscellaneous S T F S S S S T F S S S S T F S S S S T F S S S S	1. Pu	iblic Land Survey	T R T R			The second secon
Alan L. Scheppelman in a field survey on Septembor 5 19 96 do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in contomance with regulations and rules therefore as required in the universal state of the North States Experiment of the therior. Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Morth gates Experiment of the Interior. Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Morth gate Board of Land Surveyers on by a decree of a Court of Law and/or that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Morth gate Board of Land Surveyers on by a docree of a Court of Law and Court of Law and Law a	in 3. M	Section S iscellaneous S	T R T R		Register of Deeds	Stamp & File Number
A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S.  A. OSET QUARTER SECTION POST  MARCE 19, 1825  W. OAK 28, N37W, 172 LINKS (113.52*)  HICKORY 6, 5½n, 276 LINKS (182.16*)  HAY-JULY, 1885  MAY-JULY, 1885  HAY-SEAR AND NO CLAY TILE WAS FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS WERE AT A DEPTH OF 3.0*± AND 3.3*± AND NO CLAY TILE WAS FOUND UNDERNEATH THEN. ACCEPTED THE FORITON OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT BOK.  RESTALLED TO THE REBAR AS THE CORNER OF TELEPHONE FOLE  SIGNEY POUND 604 NAIL IN THE MEAST SIDE OF 4					2 6 5-	E F G H   J K L M
On this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S. 40.00 SET QUARTER SECTION POST MARCH 19, 1825 N. OAK 28, N37W, 172 LINKS (182.16')  H. F. BEAN CORNER DOWN, FOUND ONE WITNESS. MAY—JULY, 1885 MAPLE 12, N75-W, 45% LINKS (30.03') MAPLE 12, S35W, 84½ LINKS (30.03') MAPLE 12, S35W, 84½ LINKS (30.03') MAPLE 12, S35W, 84½ LINKS (55.77')  CONTINUED ON BACK  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  ON 9-5-96 EXCAVATED WITH A BACKHOE AND FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS UNDER A 1/2" X 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0'± AND 3.8'± AND NO CLAY TILE WAS FOUND UNDERNEATH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP STANDED "C-1 O'TS RIW LS NO. 35998" IN MONUMENT BOX.  N23°E POUND 60d NAIL IN THE NEST SIDE OF 26" MAPLE 69.68' N70°E SW CONNER OF CONCRETE ELOCK NILK HOUSE 120.19 S15°W FOUND 60d NAIL IN THE NEST SIDE OF TELEPHONE POLE 18.8' SUPREYOR S15°W FOUND 60d NAIL IN THE WEST SIDE OF 32" MAPLE 58.08' SUPREYOR S15°W NAIL & TAG \$35998 IN THE NORTH SIDE OF 32" MAPLE 134.35' N70°W SURVEY MARKER SION POST NATURE NATURE SIDE OF POWER POLE 104.46' S5998  Date 11/02/96	do here in lines curren Manag above Court	eby certify that under requirements 1 and 2 above were in confort manual of survey instructions dement or by a decree of a Court owere in conformance with the rurof Law; established, re-estab	nts of P.A. 74, Michigan P.A. mance with regulations ar of the United States Depar of Law and/or that the corne les of the Michigan Board (	of 1970, the corner points ment of rules therefore as required timent of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre	tioned 6 18 17 17 18 18 19 18 19 19 19 19 19 19 19 19 19 19 19 19 19	16 15 14 13 24 25 28 27 26 25
A. Description of original monument and accessories and/or subsequent restoration:  HERVEY PARKE, D.S. 40.00 SET QUARTER SECTION POST MARCH 19, 1825 W. OAX 28, N37W, 172 LINKS (113.52')  HICKORY 6, S4W, 276 LINKS (182.16')  H. F. BEAN CORNER DOWN, FOUND ONE WITNESS.  MAY-JULY, 1885 MAPLE 12, N754W, 454 LINKS (30.03')  MAPLE 12, S35W, 844 LINKS (55.77')  CONTINUED ON BACK  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  ON 9-5-96 EXCAVATED WITH A BACKHOE AND FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS UNDER A 1/2" X 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0'-1 AND 3.8'-1 AND NO CLAY TILE WAS FOUND UNDERNEATH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY NONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP GYNAMICD "C-10 TIE RIW LG NO. 35998" IN MONUMENT BOX.  N32°E FOUND 60d NAIL IN THE MEST SIDE OF 26" MAPLE  106.19  N70°E SW CORNER OF CONCRETE BLOCK MILK HOUSE  833°E FOUND 60d NAIL IN THE MEST SIDE OF 36" MAPLE  101.8!  SOCIETY NAIL & TAG #35998 IN THE NORTH SIDE OF 78" MAPLE  101.8!  SOCIETY NAIL & TAG #35998 IN THE NORTH SIDE OF 78" MAPLE  101.8!  SOCIETY NAIL & TAG #35998 IN THE NORTH SIDE OF POWER POLE  104.46' CENTERLINE "X" OF ROADS N-S-W IS 20" SOUTH AND 1.5' EAST  Date  11/02/96	NOTE		all in the same town a	nd range, may be recorded	12 31 32	33 34 35 36
MARCH 19, 1825  W. OAR 28, N37M, 172 LINKS (113.52') HICKORY 6, 54W, 276 LINKS (182.16')  H. F. BEAN  CORNER DOWN, FOUND ONE WITHESS.  MAY-JULY, 1885  MAPLE 12, N754W, 454 LINKS (30.03')  MAPLE 12, S35W, 844 LINKS (55.77')  CONTINUED ON BACK  B. Description of corner evidence lound and/or method applied in restoring or reestablishing corner:  ON 9-5-96 EXCAVATED WITH A BACKHOE AND FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS UNDER A 1/2" x 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0'± AND 3.8'± AND NO CLAY TILE WAS FOUND UNDERNEARTH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" x 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP STAMPED "C-10 TIS RW LS NO. 35998" IN MONUMENT BOX.  N23°E FOUND 60d NAIL IN THE WEST SIDE OF 26" MAPLE 69.68'  N76°E SW CORNER OF CONCRETE BLOCK NILK HOUSE 126.19'  S00°E FOUND P.K. NAIL IN THE WORTH SIDE OF TELEPHONE POLE 126.8'  S15°W FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE 58.08'  S15°W NAIL & TAG #35998 IN THE NORTH SIDE OF 32" MAPLE 134.35'  N70°W SURVEY MARKER SIGN POST 34.9'  N5998  Date 11/02/96  Signed by Asserting Post 120' SOUTH AND 1.5' EAST  Date 11/02/96  Signed by Asserting Post 11/02/96	A. D	escription of original monum	ent and accessories an	d/or subsequent restoration		
MAY-JULY, 1885  MAPLE 12, N75-W, 45-% LINKS (30.03')  MAPLE 12, S35W, 84-% LINKS (55.77')  CONTINUED ON BACK  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  ON 9-5-96 EXCAVATED WITH A BACKHOE AND FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS UNDER A 1/2" X 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0'± AND 3.8'± AND NO CLAY TILE WAS FOUND UNDERNEATH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP STAMPED "C-10 TIS RIW LS NO. 35998" IN MONUMENT BOX.  N23°E FOUND 604 NAIL IN THE WEST SIDE OF 26" MAPLE 69.68'  N78°E SW CORNER OF CONCRETE BLOCK MILK HOUSE 126.19'  S33°E FOUND 604 NAIL IN THE WEST SIDE OF TELEPHONE POLE 21.88': SCHEPPELMAN PROCESSIONAL SSI3°E FOUND 604 NAIL IN THE WEST SIDE OF TELEPHONE POLE 21.88': SWEWYOR SIS'S FOUND 604 NAIL IN THE WEST SIDE OF TELEPHONE POLE 101.81'  S65°W NAIL & TAG #35998 IN THE NORTH SIDE OF JOE MAPLE 58.08': SWEWYOR NOS'S SET NAIL & TAG #35998 IN THE NORTH SIDE OF JOE MAPLE 134.35'  NOS'S SET NAIL & TAG #35998 IN THE NORTH SIDE OF PONER POLE 104.46'  S5998  Signed by Date  Date  11/02/96	•	•	W. OAK 28, 1	N37W, 172 LINKS (11:	3.52')	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  ON 9-5-96 EXCAVATED WITH A BACKHOE AND FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS UNDER A 1/2" X 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0'± AND 3.8'± AND NO CLAY TILE WAS FOUND UNDERNEATH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP STAMPED "C-10 T1S RIW LS NO. 35998" IN MONUMENT BOX.  N23°E FOUND 60d NAIL IN THE WEST SIDE OF 26" MAPLE 69.68' N78°E SW CORNER OF CONCRETE BLOCK MILK HOUSE 126.19' S80°E FOUND P.K. NAIL IN THE NORTH SIDE OF TELEPHONE POLE 21.88' S33°E FOUND 60d NAIL IN THE WAST SIDE OF 36" MAPLE 58.08' S15°W FOUND 60d NAIL IN THE WAST SIDE OF 32" MAPLE 101.81' S65°W NAIL & TAG #35998 IN THE NORTH SIDE OF 32" MAPLE 104.46' CENTERLINE "X" OF ROADS N-S-W IS 20' SOUTH AND 1.5' EAST  Signed by Date 11/02/96  Signed by Date 11/02/96  Signed by Date 11/02/96			MAPLE 12, N	75½W, 45½ LINKS (30	.03')	
ON 9-5-96 EXCAVATED WITH A BACKHOE AND FOUND A CLUSTER OF 6 PIECES OF 2 COMPLETE FIRECLAYS UNDER A 1/2" x 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0"± AND 3.8"± AND NO CLAY TILE WAS FOUND UNDERNEATH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" x 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP STAMPED "C-10 TIS RIW LS NO. 35998" IN MONUMENT BOX.  N23°E FOUND 60d NAIL IN THE WEST SIDE OF 26" MAPLE  S80°E FOUND F.K. NAIL IN THE NORTH SIDE OF TELEPHONE POLE  S15°W FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE  S15°W FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE  S15°W FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE  S15°W FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE  S15°W SURVEYOR SURVEY MARKER SIGN POST  N70°W SURVEY MARKER SIGN POST  N65°W SET NAIL & TAG #35998 IN NE SIDE OF POWER POLE  S1998  Signed by Date  Date  11/02/96		CONTINUED ON BACK				
FIRECLAYS UNDER A 1/2" X 18" REBAR IN A MONUMENT BOX. THE FIRECLAYS WERE AT A DEPTH OF 3.0'± AND 3.8'± AND NO CLAY TILE WAS FOUND UNDERNEATH THEM. ACCEPTED THE POSITION OF THE REBAR AS THE CORNER. SET A JACKSON COUNTY MONUMENT AND BURIED THE FIRECLAY PIECES AROUND THE MONUMENT.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP STAMPED "C-10 TIS RIW LS NO. 35998" IN MONUMENT BOX.  N23°E FOUND 60d NAIL IN THE WEST SIDE OF 26" MAPLE 69.68'  N78°E SW CORNER OF CONCRETE BLOCK MILK HOUSE 126.19'  S80°E FOUND F.K. NAIL IN THE NORTH SIDE OF TELEPHONE POLE 21.88'  S93°E FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE 58.08'  S15°W FOUND 60d NAIL IN THE WEST SIDE OF 48" MAPLE 101.81'  S65°W NAIL & TAG #35998 IN THE NORTH SIDE OF 32" MAPLE 134.35'  N5998  Signed by Date 11/02/96  Signed by Date 11/02/96	B. D	escription of corner evidence	e found and/or method	applied in restoring or rees	stablishing corner:	
4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY REMONUMENTATION CAP  STAMPED "C-10 T1s RIW Ls No. 35998" IN MONUMENT BOX.  N23°E FOUND 60d NAIL IN THE WEST SIDE OF 26" MAPLE  S80°E SW CORNER OF CONCRETE BLOCK MILK HOUSE  S80°E FOUND P.K. NAIL IN THE NORTH SIDE OF TELEPHONE POLE  S33°E FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE  S15°W FOUND 60d NAIL IN THE EAST SIDE OF 48" MAPLE  S15°W FOUND 60d NAIL IN THE EAST SIDE OF 48" MAPLE  S65°W NAIL & TAG #35998 IN THE NORTH SIDE OF 32" MAPLE  NO.  35998  Signed by  Date  11/02/96		FIRECLAYS UNDER A DEPTH OF 3.0°± AND THE POSITION OF TH	1/2" X 18" REBAR 3.8'± AND NO CLA E REBAR AS THE CO	IN A MONUMENT BOX. AY TILE WAS FOUND UI ORNER. SET A JACKS	THE FIRECLAYS WE	RE AT A CCEPTED
STAMPED "C-10 T1S RIW LS NO. 35998" IN MONUMENT BOX.  N23°E FOUND 60d NAIL IN THE WEST SIDE OF 26" MAPLE  N78°E SW CORNER OF CONCRETE BLOCK MILK HOUSE  S80°E FOUND P.K. NAIL IN THE NORTH SIDE OF TELEPHONE POLE  S33°E FOUND 60d NAIL IN THE WEST SIDE OF 36" MAPLE  S15°W FOUND 60d NAIL IN THE EAST SIDE OF 48" MAPLE  S65°W NAIL & TAG #35998 IN THE NORTH SIDE OF 32" MAPLE  NO.  35998  N65°W SET NAIL & TAG #35998 IN NE SIDE OF POWER POLE  CENTERLINE "X" OF ROADS N-S-W IS 20' SOUTH AND 1.5' EAST  Signed by  Date  11/02/96	C. D	•				e corner:
Signed by Clark Jenny Date Date		STAMPED "C-10 T1S  N23°E FOUND 60  N78°E SW CORNE  S80°E FOUND P.  S33°E FOUND 60  S15°W FOUND 60  S65°W NAIL & T  N70°W SURVEY M  N65°W SET NAIL	RIW LS NO. 35998 Pd NAIL IN THE WEST OF CONCRETE BLOWN R. NAIL IN THE WEST OF THE WASTE WA	" IN MONUMENT BOX. ST SIDE OF 26" MAPLE OCK MILK HOUSE ORTH SIDE OF TELEPHO ST SIDE OF 36" MAPLE ST SIDE OF 48" MAPLE NORTH SIDE OF 32" I	E 69.6 126.1 ONE POLE 21.8 E 58.0 E 101.8 MAPLE 134.3 34.9 OLE 104.4	SCHEPPELMAN PROFESSIONAL SURVEYOR No. 35998
35998	Siana	aby Mal	Cahama C	Date	11/02/96	
	-		35998		FORM APPROVED BY MICHIGAN STAT	E BOARD OF LAND SURVEYORS, JAN. 28, 1971

C-10, T1S, R1W

A. JACKSON COUNTY ROAD COMMISSION UNDATED

MAPLE 24" S55°30'W 77.4' ELM 30" S27°00'E 57.6'
MAPLE 14" N25°00'E 69.4' MONUMENT BOX SET THE INDEX CARD ALSO LISTS ALL OF R. GUTEKUNST WITNESSES IN "C" FROM HIS LCRC.

RICHARD E. GUTEKUNST RLS 7863 APRIL 7, 1978

L.C.R.C. - LIBER 4, PAGE 229 FOUND IRON IN MONUMENT BOX

ADDITIONAL WITNESSES IN "A" ELM 40" S25°30'E 59.2'
MAPLE 36" S54°W 77.1' BUTTERNUT 24" N47°E 60.5

WITNESSES IN "C"

N23°E 26" MAPLE 69.8'
N78°E SWC CONC. BLOCK MILK HOUSE 126.2' S33°E 24" MAPLE 58.50' S15°W 41" MAPLE 102.93' S54°W 45" MAPLE 79.51'

N25°E 30" MAPLE 69.85

PETER P. KURZY RLS 5591 APRIL 1, 1977

4.4

CERTIFICATE OF SURVEY, L. 1049, P. 793 1/2" IRON PIPE IN MONUMENT BOX \$45°W 50" MAPLE 79.52' \$15°W 46" MAPLE 102.97' \$25°E 30" MAPLE 58.50'