

**JACKSON COUNTY  
APPROVED LAND CORNER  
P.A. 348 of 1990**

Chairman Alan K. Gilbertson  
Date SEPT. 9, 1998

East 1/4 Corner of Section 30, Summit Township  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

**SURVEY &  
REMONUMENTATION**

JAN 27 1999

For corners in  
JACKSON  
(County)

Located In:

Corner Code #

SECTION

1. Public Land Survey

T	3S	R	1W
T	_____	R	_____
T	_____	R	_____
T	_____	R	_____
S	_____	T	_____
S	_____	T	_____
S	_____	T	_____
S	_____	T	_____

✓  
C-10  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



2087046  
Page: 1 of 1  
09/10/1998 11:08  
L-1580 P-52

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	P
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

1. David E. Erickson in a field survey on April 1, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

In 1825, H. Parke - Deputy Surveyor, set a "Post" and recorded two witnesses: "W. Oak 12, S40°E, 34" (22.44') and "W. Oak 7, N47°W, 45" (29.70').

Around 1886, H.F. Bean reported "Post out, One good witness left" and recorded two witnesses: "Maple 10, S6°W, 39 1/2" (26.07') and "Br. Oak 8, N67°W, 139" (97.24').

Corner not recorded under Public Act 74.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Fire Clay (FC) down 0.8' in monument box. Also found small pieces of brick around FC. Accepted found FC as a careful and faithful perpetuation of the original corner position. Replaced FC with a standard Harrison cast iron monument, down 0.3' in existing monument box. Did not bury FC due to box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Harrison cast iron monument with cap stamped "#29245" in monument box.

N 56° E	Found nail, Southeast side power pole	54.03'
S 60° E	Found nail, North side 18" Oak	45.05'
S 28° E	Found nail, East side 24" Maple	29.87'
S 21° W	Center of steel fence post	37.76'
South	County Surveyor sign post	20.0'
North	Horton Road centerline	3.5'

NOTE: Bearings are magnetic



Signed by David Erickson Date 9-8-98

Surveyor's Michigan License No. 29245

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 25, 1971

REVISED MAY 14, 1975  
REVISED JAN. 1983  
ADAPTED FOR WORD PROCESSING MARCH, 1983