JACKSON COUNTY 553R OTHER CORNER CLARK LAKE MEANDER CORNER #5. APPROVED LAND CORNER COLUMBIA TOWNSHIP CODE = P.A. 345 of Chairman LAND CORNER RECORDATION CERTIFICATE #2031952 Dato A Liber 1540 Page 133 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in of 2 Page 1 JACKSON Jackson Co., MI Located In: Corner Code ## SURVEY & Recorded REMONUMENTATION 04/10/97 08:11A # 001 745 R 1 E 1. Public Land Survey Mindy Reilly R Register of Deeds APR 0 7 1998 R R R 2. Property Controlling SECTION R in Section 9 \_ T . Miscellaneous S Т Register of Deeds Stamp & File Number Property in Sec. \_ , Recorded Plat \_ Private Claims DEAN R. GUTEKUNST , in a field survey on February 25, to hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land tanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as 10 xpressed below: 11 IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Robert Clark, Deputy Surveyor, 1824. 30 links (19.80') 37 links (24.42') West corrected between Section 17 & 20, N 3½ E S 7 E Poplar 8" Hickory 8" 3.1 to a lake (3.1 chains = 204.6)No perpetuation found for the 1880's. Perpetuation by W. G. Fargo, 1893, on the plat of Eagle Point (Liber 5 of Plats, Page 12, Jackson County Records)
of Section 17, T4S, R1E.
\* Sycamore 7" S 75 Plat shows MP #5 as being 201.25' West of Southeast corner S 75 E 9 1/3 links (6.16') W. Oak 14"  $(8.085^{\circ})$ S 263 W 12 links Continued on back, Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found the 1" X 4' solid bar with a ring on top as set in 1955 by Riley. Found a 3/4" iron pipe and a rerod beside the 1" bar and small pieces of brick. Corner is approximately 16' East of the present shore line of Clark Lake, and at the surface of the lawn. Accepted the 1" X 4' solid bar as a careful and faithful perpetuation of the position of the original corner, as remonumented by Riley in 1955. Set a Standard Jackson County Monument to replace the solid bar, and left the solid bar on the North side of the monument, and the 3/4" iron pipe and rerod on the East side. Description of monument for corner and accessories established to perpetuate locating the position of the corner: MEANDER POST #5,@ Clark Lake, T4S,R1E Corner is a 4" diameter X 36" concrete monument with a ½" X 36" steel rod and an aluminum cap stamped IS 18658, which is the standard monument for Jackson County. S 75° E 40d & washer on South side. 6.16' 30" Sycamore 'nΕ S 100 E 12" W. Oak 69.98' 40d & washer on West side. и 30° Е 15" Pine 48.15' 40d & washer on West side. S 750 W Northwest corner concrete well pit 12.7 N 80° E Southwest corner foundation house 66.62 GUTEKUNST No. 18455 April 1, 1997

Date

ned by

veyor's Michigan License No. .

18658

Record 381

REVISED MAY 14, 1975 REVISED JAN 1983

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVETORS, JAN. 28, 1971

Continued,

Meander Post #5 Clark Lake

13 ......

Columbia Township T4S, R1E

- Perpetuation by W G Fargo or F. C. Riley, #377, date unknown.

\* Sycamore 9" S 75 E 9 1/3 links (6.16') Crooked W. Oak 14" S  $26\frac{1}{2}$  W  $12\frac{1}{4}$  links (8.085') Hickory 18" N  $41\frac{1}{2}$  E 46 3/4 links (30.855') 201.25' West of Section Corner Iron stake and brick

Perpetuation by F. C. Riley, #377, dated 1955. Found old iron, OK Set a  $1\frac{1}{4}$ " X 4' solid iron with a ring on top.

