

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

**SURVEY &
REMONUMENTATION**

FEB 26 2001

For corners in

KALKASKA

(County)

Located In:

Corner Code #

SECTION

2000 REMONUMENTATION

1. Public Land Survey

T.25N R.5W

D-9

T. R.

T. R.

T. R.

T. R.

**2. Property Controlling
in Section**

S. T. R.

S. T. R.

**3. Miscellaneous
Property in Sec.**

S. T. R.

S. T. R.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, EUGENE FARRIER, in a field survey on August 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-9: 1/4 Cor. Common to Secs. 20 & 29, T25N-R5W, Garfield Township

1852, GLO resurvey by George H. Cannon set post for corner; Sugar 16" N 58° E 30 links; Sugar 11" S 65° W 39 links.

1902 Survey by Merrill, Co. Surveyor, Book 17 pages 65-66 Iron pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-9: 1/4 Cor. Common to Secs. 20 & 29, T25N-R5W, Garfield Township

Found 5/8" Iron and Cap 2.9' N of centerline E-W road and 1' W of N-S fences. On line between section corners and 0.86' off split. No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-9: 1/4 Cor. Common to Secs. 20 & 29, T25N-R5W, Garfield Township

Found 5/8" Iron and Cap 2.9' N of centerline E-W road and 1' W of N-S fences. Added 5/8" Iron and brass cap in mon box.

S 55° E, 3.15', found 1/2" iron.

N 20° W, 43.92', power pole, found nail

S 02° W, 34.92', steel fence corner post, found nail

S 52° W, 44.49', 24" Maple, found nail

N 10° E, 38.29', corner fence post, found nail

Kalkaska County Peer Group accepted the above monument as the best available evidence of the position of the original corner.

Ratified by Peer Group

P.A. 345 - 1990 Kalkaska County

Chairman Eugene Farrier

Date 2-14-01

Signed by Eugene Farrier

Surveyor's Michigan License No. 24594

Date 2-15-01



3026807

Page: 1 of 1

02/15/2001 10:26A

REMON

LB: 6 PG: 136

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1996