

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

KALKASKA Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
 (County)  
**2000 REMONUMENTATION**  
 1. Public Land Survey T 25N R 5W E-9  
                                   T \_\_\_\_\_ R \_\_\_\_\_  
                                   T \_\_\_\_\_ R \_\_\_\_\_  
                                   T \_\_\_\_\_ R \_\_\_\_\_  
 2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
    in Section           S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 3. Miscellaneous       S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
    Property in Sec.     S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

**SURVEY &  
 REMONUMENTATION**

**FEB 26 2001**

**SECTION**

I, EUGENE FARRIER, in a field survey on August 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-9: Sec. Cor. Common to Secs. 20, 21, 28 & 29, T25N-R5W, Garfield Township

1852 GLO Resurvey by George H. Cannon set post for corner; W. Pine 24" S 20° W 38 links; Maple 6" N 49° E 15 links.

1978 LCRC Norman Parker Liber 2 Page 39, found 1/2" bar used in previous surveys of record; spike and washer SW side power pole S 29° E 50.00'; Stop sign post N 21° W 39.00'; Corner is in centerline of road inter.

1991 LCRC Philip Case Liber 2 Page 432, bolt spike; S 30° E P.P. 50.01'; S 40° W 16" Tw. Maple 153.15'; S 21° W 24" R. Oak, 254.99'; N 10° E Road Sign 56.10'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-9: Sec. Cor. Common to Secs. 20, 21, 28 & 29, T25N-R5W, Garfield Township

Found bolt spike from Liber 2 Page 432 in centerline E-W and N-S roads S 30° E, 50.01'; found nail in P.P; N 10° E, 51.10' Road sign post. No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9: Sec. Cor. Common to Secs. 20, 21, 28 & 29, T25N-R5W, Garfield Township

Found bolt spike in centerline E-W and N-S roads. Added 5/8" iron and brass cap in mon box.

S 30° E, 50.01' nail in power pole found

S 20° W, 60.3', sign post, found

N 63° E, 56.60', 7" Cherry, found nail

N 10° E, 51.10', Road sign post

N 10° W, 49.35', wood post

S 45° W, 54.08', corner fence post

Kalkaska County Peer Group accepted the above monument as the best available evidence of the position of the original corner.

Ratified by Peer Group  
 P.A. 345 - 1990 Kalkaska County

Chairman Eugene Farrier

Date 2-14-01

Signed by Eugene Farrier  
 Surveyor's Michigan License No. 24594

Date 2-15-01



**3026808**  
 Page: 1 of 1  
 02/15/2001 10:25A  
 REMON  
 LB: 8 PG: 137

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1976  
 REVISED JAN., 1983  
 REVISED OCT., 1996

