

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALKASKA

Located in:

Corner Code #

(County)

2000 REMONUMENTATION

1. Public Land Survey

T 25N R 5W

I-9

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, EUGENE FARRIER, in a field survey on August 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-9: Sec. Cor. Common to Secs. 22, 23, 26 & 27, T25N-R5W, Garfield Township

July 28, 1852 GLO Resurvey by George H. Cannon, set post for corner; Sp. Pine 12" S 48° W 22 links; Sp. Pine 8" N 10° E 17 links.

May 5, 1981 Survey by Eugene D. Farrier, set 1/2" iron and cap centerline Fletcher Road N-S and S. Pine Road E-W, 8' E of centerline N-S trails; N 40° W 46.58', 1/2" iron and cap; S 30° W Conc. Mon. Ref. To MDSH horiz. Control point, 55.21'; S 64° W Conc. Mon. Ref. To MDSH horiz. Control point, 55.21'; S 64° W Conc. Mon. Ref. To MDSH horiz. Control point, 69.84'; North 1/2" Iron and cap, 308.80'.

May 7, 1981 LCRC Eugene D. Farrier Liber 2 Page 307, set 1/2" rod and cap #24594 8' E of Centerline N-S trails held Centerline Fletcher Road N-S and single proportioned E-W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-9: Sec. Cor. Common to Secs. 22, 23, 26 & 27, T25N-R5W, Garfield Township

Found iron and cap #24594 recorded in Liber 2 Page 307 in centerline E-W Road and 7' E on N-S trails; N 38° W, 46.58', found iron and cap #24594. No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9: Sec. Cor. Common to Secs. 22, 23, 26 & 27, T25N-R5W, Garfield Township

Found iron and cap #24594 recorded in Liber 2 Page 307 in centerline E-W Road and 7' E on N-S trails; added 5/8" iron with brass cap in mon box.

S 32° W, 54.91' MDOOT control point in 12" Concrete monument leaning

S 56° W, 61.32' 03" pipeline marker #24

N 38° W 46.58' Iron and cap #24594 found

N 33° E, 47.60' set nail and washer in 4" J. Pine

S 20° E, 75.69' set nail and washer in 4" J. Pine

Kalkaska County Peer Group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

Ratified by Peer Group

P.A. 345 - 1990 Kalkaska County

Chairman

Date

Signed by
Surveyor's Michigan License No. 24594

Date 2-15-01



Kalkaska County Joan Hall, Register

3026812
Page: 1 of 1
02/16/2001 10:28A
REMON
LB: 8 PG: 141

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS
RECEIVED
OCT., 1995