LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:	Located In	n Corner Coo	do 44	
(County)	Located in	1 Corner Coo	ue#	
Public Land Survey		5W H7		
Property Controlling in Section	T R S T R			
Miscellaneous Property in Section	S T R			
4 Lah Na		× ×	L	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:			A B C D E F G H I J K L M
5. Private Claims:				2 6 5 - 4 - 3 - 2 - 1 -
I, Craiq W. McVean, in a field survey on October 4, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				11
				13
A. Description of original monument and accessories and/or subsequent restoration:				
H7 - 1852 - GLO - Cannon - Set qr. Sec. post, 1) W Pine 16" N52°W 60, 2) W Pine 14" S39°E 83				
- 1957 - DNR corner record – B. D. Buckler, PS #8887 – This corner was found by forestry division survey crew while making a partial resurvey of this township. Found ½" iron bar in place, presumably by G. F. DeLaMater, with sites for both government BT's accepted as ¼ corner, having no evidence to the contrary 1" pipe with 4" brass cap set at ½" iron bar, 3) 7" B. Oak N41°E 83 L., 4) 5" B. Oak S62°E 34½ L., 5) 12" B. Oak S18°W 108 L.				
- 1978 – Consumer's Power Co. Survey drawing #S-F17406 – DAA – Found 1" pipe with 4" brass cap, 3) 7" B. Oak N41°E 83 L., 4) 5" B. Oak S62°E 34½ L., 5) 12" B. Oak S18°W 108 L.				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
H7 – ¼ Corner common to sections 15 & 22, T26N, R5W – Found 4" Department of Conservation Brass Cap Monument of 1" iron pipe. Found witnesses #3, & #4, and stump remains of witness #5. 4" DOC Monument accepted as a careful and faithful perpetuation of the position of the original corner.				
C. Description of monum	ent for corner and acces	sories established to	perpetuate loc	cating the position of the corner:
H7 – 4" DOC Brass Ca	ap on 1" galv. iron pipe	e. Set Blue carsonit	e Post 1' No	orth.
S59°E 22.60' to t S48°W 17.63' to t	found nail in W side 10 found nail in SW side 1 found nail in SE side 1 found nail in N side 11	12" Oak (#4) 0" R. Pine		CRAIG W. MGVEAN PROFESSIONAL SURVEYOR No.
46			4)	39088 39088 STEP
	ring M. W.	Me Den	Date:	1/20/2011
Surveyor's Michigan L	icense No.: 390	88	~	