## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Kalkaska (County)	Located In (	Corner Code #
1. Public Land Survey	T 26N R 5W	1-9
Property Controlling in Section	S T R	
Miscellaneous     Property in Section	S T R	
	S R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	ABCDEFGHIJKLM
5. Private Claims:		2 6 - 5 - 4 - 3 - 2 - 1
under requirements of PA	field survey on <u>September 27, 2010</u> do 74, Michigan PA of 1970, the comer p e in conformance with regulations and	points mentioned in 4 7 8 9 10 11 12
required in the current mar of the Interior, Bureau of L	nual of survey instructions of the United S and Management or by a decree of a C	d States Department 5 18 17 16 15 14 13 Court of Law and/or 5 18 17 16 15 14 13 13 14 15 15 14 15 15 16 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18
the rules of the Michigan B	Interior, Bureau of Land Management or by a decree of a Court of Law and/or the corner points mentioned in lines 3, 4 and 5 above were in conformance with teles of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; lished, re-established, monumented, recovered, found as expressed below:  6 18 17 16 15 14 13 17 16 15 14 17 16 15 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18	
		9

- A. Description of original monument and accessories and/or subsequent restoration:
- 1-9 1852 GLO G. Cannon Set post corner of sec. 22, 23, 26 & 27,

NOTE: Not more than 2 corners, all in the same town and range, may

- 1) SP. Pine 6" N55°W 31 2) SP. Pine 5" S55°E 7

be recorded on this certificate.

- 1957 DNR corner record B. D. Buckler, PS #8887 This corner was established by double proportionate measurement, by forestry division survey crew while making a partial resurvey of this township. Corners 1 mile North, 1 mile West, and 2 miles East were used in the proportion. No evidence of government BTs. - set 1" pipe with 4" brass cap, 3) 8" J. Pine N64°E 621/2 L., 4) 7" J. Pine N30°W 511/2 L., 5) 8" J. Pine S17°W 11L.
- 1969 Consumer Power Co. Drawing No. SF17310 E. McCombs Corner found.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 1-9 Corner common to sections 22, 23 26, & 27, T26N, R5W Found bent and broken 4" Department of Conservation Brass Cap Monument on 1" iron pipe in recently burned Jack pine stand. Found stump remains of Witnesses #4 & 5. No evidence of GLO Witnesses. 4" DOC Monument accepted as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1-9 Replaced Broken 4" DOC Brass Cap on 1" iron pipe with stamped 4" DNR Alum. Cap on 1" x 3' long galv. iron pipe. Set Blue carsonite Post 1' North,

North 32.86' to set 1/2" X 18" rebar N88°E 35.62' to set 1/2" X 18" rebar S08°E 37.21' to set 1/2" X 24" rebar S83°W 39.66' to set 1/2" X 18" rebar

Surveyor's Michigan License No .:

OF MICHIG CRAIG W. McVEAN ROFESSIONAL SURVEYOR No. 39088 OFESSION