

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALKASKA  
(County)

Located In:

Corner Code #

2000 REMONUMENTATION

1. Public Land Survey

T 27N R 7W

K-2

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

1. EUGENE FARRIER, in a field survey on August 29, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-2: 1/4 Cor. Common to Secs. 1 & 2, T27N-R7W, Kalkaska Twp

1850: GLO resurvey by Lucius Lyon, set Beech post for 1/4 corner; Beech 12", N 37.5°W, 14 links; Sugar 12", S 82°E, 10 links.

1888: Survey by E. Mosher in Book 50 Page 4; tie into corner only.

1988: Survey by M.E. Myers in Liber 3 Page 371; found 1/2" bar and cap #14102 at corner; set 1/2" x 18" steel bar east 33.01'; no other accessories given.

1997: Survey (not recorded) by D.R. Farrier, found iron and cap at corner; matches distance by M.E. Myers to south to section corner within 0.28'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-2: 1/4 Cor. Common to Secs. 1 & 2, T27N-R7W, Kalkaska Twp

Found 1/2" iron rod 4' east centerline Wheeler Lake Road, added standard County Monument.  
No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-2: 1/4 Cor. Common to Secs. 1 & 2, T27N-R7W, Kalkaska Twp

Found 1/2" iron rod 4' east centerline Wheeler Lake Road, added standard County Monument.  
N 55°E, 48.17', power pole, set nail and tag  
East 32.97', iron and cap #31600  
S 72°W, 74.30', 8" Red Pine, set nail and tag  
N 44°W, 60.44', 12" Cherry, set nail and tag

Kalkaska County Peer Group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		10		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



Signed by Eugene D. Farrier  
Surveyor's Michigan License No. 24594

Date 2-15-01

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971  
REVISED MAY 14, 1976  
REVISED JAN., 1982  
REVISED OCT., 1985

Ratified by Peer Group  
P.A. 345-1990 Kalkaska County

Chairman Eugene D. Farrier  
Date 2-14-01



**3026895**

Page: 1 of 1  
02/15/2001 10:28A  
REMON  
LB: 8 PG: 224