SURVEY & REMONUMENTATION

APR 27 1995

expressed below:

Surveyor's Michigan License No. .







STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 94 DEC 28 PM 2: 15

For Comers in	F 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	a service de la companya de la comp	
Kent	Located In:	Corner Code ++	Lui John Co
(County)			REG. OF DEEDS
1. Public Land Survey	T 5N R 12W	<u>L-6</u>	
÷	<u>T</u>	The second of the second	
	T 8		
2. Property Controlling	S T R	- 1. Section 1 - 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	7921
in Section	STR	- <u>1 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - </u>	
3. Miscellaneous	S TR		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No,	Recorded Plat		АВС D E F G H I J K L I
5. Private Claims			
			3
	, ;;		4 7 8 9 10 11 12
, Douglas W. Bonnem	la in a field survey on Nov.	16 19 94	5 1 1 1 1 1 1 1

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

*Since this is not a government corner, there is no G.L.O. information.

Williams & Works 1941 Used fence cornernot an extensive survey

Exxel Engineering 1986 Set iron at intersection of 1/4 lines. Nail in N sde 4" Maple West 27.39' Nail in SW sde 12" Birch SE 30.70' Nail in S sde 4" Maple East 32.19'

Nail in SE sde 4" Maple NE 51.33' Capped iron North 19.70

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Apparently the iron has been destroyed but we found all of the witnesses from 1986 and re-set the point from them.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

P.A. 345 1990 KENT COUNTY PEER APPROYED 9/22/ CHAIRMAN

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4"x30" Kent County Cast Iron Monument		
Nail & KC tag in E'ly sde 10" Ash	S20°W	24.05'
Nail & KC tag in S'ly sde 10" Ash	S71°W	12.98'
Nail & KC tag in N'ly sde 8" Maple	S84°W	27.49'
Nail & KC tag in W'ly sde 5" Ash	N35°W	14.61'
Nail & KC tag in SE'ly sde 5" Maple	N35°E	51.34'
Nail & KC tag in S'ly sde 6" Maple	N85°E	32.14'
Nail & KC tag in NE sde 16" Cedar	S45°E	38.46'
Nail & KC tag in SW sde 24" Black Beech	S31°E	30.70'
Exxel capped iron	North	19.7'
Signed by Monglas W Bonnama	۵	ate 12/14
Oligined by		· · · · · · · · · · · · · · · · · · ·

DOUGLAS W BONNEWA LAND SURVEYOR ИО ESSIONAL

REVISED JAN., 1983