

\$7.00
\$2.00

SEP 13 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12W

M-10

T R

T R

T R

T R

2. Property Controlling
In Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Randy Kolehose, in a field survey on March 17 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-10	1817	G.L.O. Notes	L. Lyon
	1966	Wit. Map	K.C. Surveyor
	1977	L.C.R.C. #1077	Williams & Works
	1981	L.C.R.C. #2141	Jonker Land Survey
	1991	L.C.R.C. #6370	Chris Marshall

Set Post
Iron on Fence Line
Found 1 1/2" Iron Pipe
Found 1 1/2" Iron Pipe/Set K.C. Monument
K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 6/27/95
CHAIRMAN Randy Kolehose

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Jonker Land Surveys on 9/22/81 and was recorded per L.C.R.C. #2141.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-10 Found standard Kent County Monument on intersection of fallen farm fences running West and North per L.C.R.C.'s #2141 and #6370 as set by Jonker Land Surveys in place of 1 1/2" iron pipe they found which checked L.C.R.C. #1077.

L.C.R.C. #2141

L.C.R.C. #6370

Remon. tag on S side 10" Elm S80°E 12.85'
Remon. tag on E side 14" Ash N10°W 26.55'
Remon. tag on SE side 14" Maple S80°W 11.45'
Remon. tag on W side 6" Ash S40°E 20.92'

Nail & Tag S sd 12" Elm S 80 E 12.87'
Nail & Tag SE sd 18" Maple S 80 W 11.48'
Nail & Tag E sd 16" Ash N 10 W 26.54'
Nail & Tag W sd 8" Ash S 40 E 20.92'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-10 Standard Kent County Monument

Nail & K.C. remon. tag on S side 12" Elm S 80° E 12.87'
Nail & K.C. remon. tag on SE side 18" Maple S 80° W 11.48'
Nail & K.C. remon. tag on E side 16" Ash N 10° W 26.54'
Nail & K.C. remon. tag on W side 8" Ash S 40° E 20.92'
Fence post (wooden) .5' NW

Signed by

Randy J. Kolehose
EARTH TECH

Date

8/21/95

Surveyor's Michigan License No.

25854

