## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	corners	in

			1					
Keweenaw	Located In:	Corner Code #						
(County)	_		***					
1. Public Land Survey	TR TR							121
2. Property Controlling in Section	S 28 T 56N R 31W S 28 T 56N R 31W S T R							
3. Miscellaneous	S T R							
Property in Sec.	STR							
4.1.411.			- 1	Register	r of Deeds Stam	np & File Num	ber	
	corded Plat	<u></u>	_	A B C	D E F G	H I J	к	L M
5. Private Claims			1				18	ŤÏ
Steps		G.	2	1 1	-5	3-1-2	3 13	1
i, Stephan J. Szyszkoski , i	n a field survey on	09/11/13 do here!	by state				1	
	74, Michigan P.A. of 1970, the cor			77	- 8 9 <u>-</u>	10-1-1	1	12
above were in conformance with	regulations and rules therefore as re	equired in the current manual	of survey 5				-	+-1
instructions of the United States	Department of the Interior, Bureau	of Land Management or by a	decree of 6	18	-1716	151/	4	13
the rules of the Michigan Road	corner points mentioned in lines 3, 4	and 5 above were in conforma	ance with 7					
re-established, monumented, recov	d of Land Surveyors or by a Devered, found as expressed below:	cree or a Court of Law; es	tablished, g	19	-2021	222	3——	24—
8 8	III		9			<del>                                     </del>		
NOTE: Not more than 2 corr	ners, all in the same town and ra		10	30	-2928	272	5	25
on this certificate.	iers, an in the same town and ra	inge, may be recorded	11		60	┝╌┼╌┼	- 1	-
on this certificate.			12	31-	_323_	_343!	5	36-
			13					
A. Description of original m	nonument and accessories and	/or subsequent restoratio	n:					
(11-Sec. 28) Southwes	st 1/16 corner, Section	28. Not previousl	v monum	ented.				

- (10-Sec. 28) South 1/16 corner between Sections 28 and 29. Not previously monumented.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (11-Sec. 28) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.
- (10-Sec. 28) Established the position for the corner midway and on the Section line between Section corner 1308.78' south and Quarter corner 1308.78' north.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. (10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 12" Cedar N67°W 33.0' mrkd "1/16S BT" 5" Maple N57°W 15.9' mrkd "1/16S BT" 12" W.Birch N31°W 21.85' do 3" Balsam N89°E 20.4' do 17" Y.Birch N64°E 8.25' do 3" Maple S32°E 9.65' do 15" Cedar N82°E 24.1' ďΩ 7" Cedar in clump \$48°W 27.4' do Set sq'd cedar post adjacent. Set sq'd cedar post adjacent. E= 7905223.810 N= 271350.122 E= 7904837.786 N= 271346.747

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum). Coord. Ref.=USACE monument "RAMP 1995": N= 268244.768 m. E= 7906171.601 m

Signed by

10/02/2013

OF MICH

SZYSZKOSKI

LAND

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PI