REPARTMENT LAND CORNER RECORDATION CERTIFICATE

_	r corners in	AUG 2 2 19		uirement	of Act 74,	Mich. P.A. 19	70	CLERK-	NUL	CELAC ALME	
	(alamazoo		Located In:	Co	orner Code =	##		系 為	σ	UE	
1.	Ross Township Public Land Surve	y	T 1 S R 9 W T R T R		E-1			- NEUISTER	AM 9 05	TOTAL ARECORD	
2.	Property Controllin		_ T R					•			
3.	in Section Miscellaneous Property in Sec.	S	T R T R T R				Register of	Deeds Star	np & Fil	e Number	
4	Lot No.	Recorded F	Plat				_				
5.	Private Claims		LIBE	R 1	130	5	_ 2		F G H		1-
				+ ·			3		- -		+
l	Robert E. Sn	ell in a field	survey onNO	vember 8	j,	19 94	4		10	11-1	12_
Ma ab	lines 1 and 2 above varient manual of survey inagement or by a decipove were in conformaniurt of Law; establish pressed below:	instructions of the ee of a Court of La ce with the rules	ne United States De aw and/or that the co of the Michigan Boa	partment of orner points ard of Land S	the Interior, E mentioned in Jurveyors or b	Bureau of Land lines 3, 4 and 5 y a Decree of a	7 81 9	9 -20 -2	21 22	23	24
NC	OTE: Not more that on this certification	,	in the same tow	n and rang	e, may be re	ecorded	11 123 13	1 32 3	3-34	35	-36
A.		I States Go	and accessories vernment Sur at intersect	vey; int	ersected	base line		ks West o	f 1/4	Section	
	Bl. 0a Wh. 0a		South South	22° 42°	East West	49 Lks 83 Lks					
		y Pratt. 'y 10"	ty Surveyor; Bored 3', pu South South							ring	
В.	Description of cor	ner evidence fo	ound and/or meth	od applied	in restoring	or reestablish	ning corner				
	1920 (CIRA.)		North d Southwest	20°	East	17.9' 36.0'					

24" Bass North 40° 39.31 West

1994: Found 3" round tile 1.3' below surface. Took witnesses.

RATIFIED BY KALAMAZOO COUNTY **REMONUMENTATION** PEER GROUP 12-15-94

SS RECO

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Northwest Corner Section 4, T. 1 S., R. 9 W., Ratified by the Kalamzoo County Remonumentation Program Peer Group on December 15, 1994 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3' round tile 1.3' below surface of the road, the tile was set by F. Hodgman in 1883 remonumentation survey. Tile was removed during road construction. Placed a 20" Harrison monument in monument box from witnesses.

Exist. Nail/Tab in East Side Power Pole North 20° East Exist. Nail/Tab in Southwest Side 27" Hickory South 50° East י37.37 86.15' Power Pole South 20° West 74.66' PK Nail in East Side South 70° West 87.41' PK Nail in North Side 15" Oak

Date _ Signed by .

Surveyor's Michigan License No. 9734

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983