

2 AUG 06 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **COMMISSION**
Kalamazoo

Located in:

Corner Code #

Ross Twp.

1. Public Land Survey

T1 S. R 9 W.

G-01

2. Property Controlling in Section

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Section

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat

5. Private Claims

1. Robert E. Snell, in a field survey on May 3, 1996.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; intersected baseline 751 lks. West of 1/4 Section post. Set post at intersection common to Sections 3 and 4.

Beech 7"	S. 78 ⁰ E.	36 1ks.
Ironwood 7"	S. 39 ⁰ E.	28 1ks.

1883: F. Hodgman, County Surveyor; found stake with stone around at intersection of fences. No witnesses. Bored 3 ft., put stone in bottom and 2 foot earthen post over it with stones around. No trees near.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1957: Wilkins & Wheaton Engr. Co.; found tile.

2" Iron Fence Post	East	498.15'
Tree with 2 tabs on face	Southwest	253.53'

1996: Found 3" round tile 18" deep using 2" iron fence post East 498.15'. Top of tile broken, capped iron on West side of tile, unable to read RLS number on cap.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
5-10-1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-01: Northwest corner of Section 3, T. 1 S., R. 9 W.; Ratified by the Kalamazoo County Remonumentation Program Peer Group on May 16, 1996, and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile with top broken, as set by F. Hodgman, County Surveyor in an 1883 remonumentation survey. Placed 18" Harrison Monument over tile.

Old North and South Fence	West	56'	
2" Steel Fence Post	East	498.15'	(1957 witness)
West Edge of Steel Fence Post	East	0.50'	
PK Nail on North Side of 14" Wild Cherry	S. 45° W.	79.87'	
PK Nail on North Side of 5" Wild Cherry	S. 89° E.	47.65'	

Signed by

Date _____

Surveyor's Michigan License No. 9734

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983