

SURVEY &  
REMONUMENTATION

7- MAY 28 1997

2- COMMISSION

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD

1996 SEP 9 PM 3 51

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Cooper Township  
Kalamazoo  
(County)

Located In:

Corner Code #

*James J. Young*  
CLERK-REGISTER

1. Public Land Survey	T	1S.	R	11W.	B-8
	T		R		
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T		R
	S		T		R
3. Miscellaneous	S		T		R
Property in Section	S		T		R

LIBER 2 PAGE 058

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

6. IWM Job Nos. 24071, 24991, 27425 & 27585

I, Allen H. McMachen, in a field survey on January, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Corner not set by Government Survey

1940 - County Surveyor

Set iron in North and South fence  
and 0.6' North of East and West  
fence. Set iron was 2652.4 feet West  
of East quarter corner and 2654.3  
feet South of North quarter corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Placed iron rod at intersection of  $\frac{1}{4}$  lines (all  $\frac{1}{4}$  corners establishing  $\frac{1}{4}$  lines previously ratified by Kalamazoo County Remonumentation Peer Group) Said iron is 1' South of old downed fence line to East. Iron at intersection is 2652.13 feet West of East quarter corner, and 2656.62 feet South of North quarter corner.

*R.E.S.*  
**RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP  
2-15-1996**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

This position not established by Orig. Government Survey. Iron rod at intersection of  $\frac{1}{4}$  lines is accepted as the best available evidence of the position of the corner.  
Replaced iron with a Harrison Monument, Accessories:

Nail & Tab in S. Side 6" Black Cherry N. 60° E. 18.23'  
Nail & Tab in S. Side 6" Black Cherry N. 80° E. 12.10'  
Nail & Tab in S. Side 6" Black Cherry S. 70° E. 15.55'  
Nail & Tab in S. Side 6" Black Cherry S. 55° E. 13.34'  
4' South of new fence to East

Signed by Allen H. McMachen

Date 9/6/96

Surveyor's Michigan License No. 16935

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

