PK Nail in West Side PK Nail in East Side PK Nail in East Side PK Nail in East Side

9734

Signed by \_

Surveyor's Michigan License No.

PEM	ONUMENTATION						
1	OCT 0 6 1997 COMMISSIO		LIBER		2PAGI	E 160	0
For corn Ka	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970  lamazoo		CLERK	H	<b>.</b> 97 JUL	COUNTY OF	STATE
	County) Located In: Corner Code #		Ι.,	<b>Ž</b> .	29	ep of	O TR
1. Publi	T_3S_R_9W K-06  T_R_ T_R_  T_R_		REGISTER	The	AM 11	F KALAMAZOO ) FOR RECORD	MICHIGA
in Sed 3. Misce	erty Controlling S T R ction S T R ellaneous S T R erty in Sec. S T R	Registe		ک eeds S	OB tamp &	RD O	
4. Lot No 5. Privat	o, Recorded Plat	ВС	D i	E F	Э н	ΙJΚ	( L )
i, Rot requirement conformant United Stat that the co Board of t	Dent E. Snell, in a field survey on May 20, 19 97 do hereby state that under this of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in the ce with regulations and rules therefore as required in the current manual of survey instructions of the tess Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for orner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, found as expressed below:	7 19 19	- 8	9161	101515	-11-	—12— —13—
	8,	_1'9	_20	—21—		23	2 <sup>1</sup> 4
A. Descri	Not more than 2 corners, all in the same town and range, may be recorded  9  RATIFIED  10  REMONUMENTATION  PEER GROUP 6-19-19-17  iption of original monument and accessories and/or subsequent restoration:  United States Government Surveyors; set 1/4 Section post.	30	-29 -32		34	-26 -35	—25— —36—
-	Beech 7" S. 44° W. 9 lks. Beech 5" S. 73° E. 10 lks.			•			
1883:	F. Hodgman, County Surveyor; "Found stake standing at angle from stump of Beech bearing tree. Bored 3 ft. in stake holestone and put 2 ft. earthen post over and noted for bearing 55 lks., and Beech 20" N. 15° E. $37\frac{1}{2}$ lks."	e. fi	Hed	the	hotto	m wit	'n
B. Descr 1975:	iption of corner evidence found and/or method applied in restoring or reestablishing corner.  Larkin Winther, RLS #13605; Survey in SW 1/4 and SE 1/4, Section for E 1/4 post.	ction	14	and p	erhap	os set	
1992:	Wilkins & Wheaton Engr. Co.; Found iron at East 1/4 post, Soin center line Road South & East 8" W. Cherry N. 42" Ash S. 40° W. 61.8' Large Stone Nor	45° E		37. 2.			
1997:	Found 3" round tile down 10" below surface. Dug to 20" and tile. Large stone East 1.86' and in approximate intersection to Southwest 2.37'	found	đ go Roa:	nd se	ction	of d Sou	th.
C. Descrip K-06:	vion of monument for corner and accessories established to perpetuate locating the position of West 1/4 post, Section 13, T. 3 S., R. 9 W., ratified by the Remonumentation Program Peer Group on June 19, 1997 and is a faithful perpetuation of the position of the original corner set in 1883 Remonumentation Survey by F. Hodgman, County Sur Monument over tile.	accep r. Fo	ted a ound	asa 3" r	caref ound	tile	

12" Maple 22" W. Cherry 4" Maple 12" Maple

North

N. 68° E. S. 18° E. S. 18° W. 40.30' 36.96' 10.93' 26.36'