## SURVEY & REMONUMENTATION

Signed by.

Surveyor's Michigan License No.

AUG 0 6 1996 COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in <u>Kalamazoo</u> Corner Code # Located In: Pavilion Twp. T 3 S. R10 W. 1. Public Land Survey \_T \_\_\_ R\_\_ 2. Property Controlling S \_\_\_\_ T \_\_\_\_ R\_\_ in Section LIBER 1PAGE1497 S \_\_\_\_ R \_ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section \_\_\_\_, Recorded Plat\_ 5. Private Claims Robert E. Snell, in a field survey on April 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1827: United States Government Surveyors; set 1/4 Section post. Tam 5" Tam. 4" 1885: F. Hodgman, County Surveyor; found stones of former survey. F. Hodgman, County Surveyor; bearing trees and all other timber near corner burned 1888: and killed. Ditch from the North in line ends here. Set earthen post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1937: Wilkins & Wheaton Engr. Co.; found tile at intersection of fences. 1996: Found tile just above ground level at fence intersection. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: South 1/4 post Section 20, T. 3 S., R. 10 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on May 16, 1996, and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile as set by F. Hodgman, County Surveyor in 1888 remonumentation survey. Placed remonumentation sleeve over tile. N. 45° W. S. 45° W. S. 20° E. S. 80° E. 0.95' Southeast corner of Railroad Rail fence corner 17.80' PK Nail on East Side 8" Oak PK Nail on East Side 8" Oak 36,60° PK Nail on South Side 12" Oak

> FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Date