FEB 1 8 1994

port of the second seco

1 PG 1085 LIBER

LAND CORNER RECORDATION CERTIFICATE

P.A. 1970

			Filing Requirement of Act 74, Mich.
For corners in	PAVILION	TWP.	

KALAMAZOO (County)	Located In:	Corner Code ##
Public Land Survey	T 3S R 10W	<u> 1-3</u>
•	T R	·
	T R	<u> </u>
	T Ř	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec	S T O	

RECORD

Register of Deeds Stamp & File Number

4.	Lot I	No.	 , Recorded	Plat
_				

U. I HYDLE CIDING	5.	Private	Claims
-------------------	----	---------	--------

I Allen H. McMachen a field survey on December 4 , 19 <u>93</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: 1888 - F. Hodgeman C.S. placed Clay Tile post during official

3		L.,		Ŀ			L					
4	L	7	_	8—	9		L-1	0	- 1	1	1	2
5	<u> </u>						Щ	_				
6	1	[8—	<u>_</u> 1	7	_1	6—-	1) 5—	1	4	L,	3—
7	<u> </u>	Ц.						<u> </u>				
8	1	9	<u>2</u>	Q	2	1	2	2—		3	2	4—
9	L											
10	3		_2	9	2	8	2	, ,	_2	6	2	5
11			\vdash			ш	_			-		
12	з	1	3	2—	<u>—</u> з	3	<u>_</u> 3] :4—	<u></u> 3) 5	3	6—

Township Remonumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Clay Tile in water.

RATIFIED BY KALAMAZOO COUNTY **REMONUMENTATION** PEER GROUP 12-16-93

ALLEN H. **McMACHEN** LAND SURVEYOR No. 16935 4ND

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Placed Standard Sleeve over existing Tile; accessories:

Set Iron Rod with Cap (1' deep) Nail in Root of 60" Willow Stump Nail in South face 10" multi-stemmed Elm Nail in South face blown down Willow Tree growing horizontally to ground

N. 35 deg. E. 33.01'

S. 15 deg. W. 8.40'

deg. W. s. 83 18.08'

s. 76 deg. E. 8.89'

Signed by Surveyor's Michigan License No.

VEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 MEVISED JAN., 1983